



Subject: Dimplex Remote Control Receiver Recall

Dear Valued Skyline Recreational Vehicle Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Skyline Corporation, on behalf of its subsidiary manufacturing facilities, has decided that a defect which relates to motor vehicle safety exists in certain recreational vehicles as described below.

2004 through 2007 model year park model trailers which were manufactured between June 1, 2003 and May 31, 2007.

The Problem:

Specifically, certain 2004 through 2007 model year park model trailer recreational vehicles may have been equipped with a defective remote control receiver. In some instances, the plug-in remote control receiver can overheat, posing a fire hazard. Skyline is not aware of any injuries or other incidents as a result of this condition.

Affected Vehicle Models:

The vehicles covered by this recall are model years 2004 through 2007 park model recreational vehicles manufactured by Skyline Corporation and their subsidiaries.

While it is our belief only a small number of vehicles are affected, it is critical that your vehicle be inspected to correctly identify the remote control receiver. You may feel comfortable making the inspection yourself. If so, the following pictures on page 3 show the identification tag as supplied by the manufacturer.

If you are at all unsure of whether your receiver is affected you should have the dealer make the inspection for you.

WHAT WE WILL DO

Skyline will provide at no charge to the customer:

- Visual inspection of the receiver.
- Replacement of affected receiver.
- Postage paid package for return and disposal of affected receiver.

WHAT YOU SHOULD DO

Since this defect affects motor vehicle safety, it is recommended that you immediately make a visual inspection of the fireplace remote control receiver on your vehicle and/or make an appointment with your selling dealer or other authorized Skyline dealer to have your vehicle inspected. In either case compare the identification tag on your receiver to the pictures above. If it appears your receiver is affected, unplug the receiver from the electrical outlet, unplug the fireplace from the receiver, make note of the model number and date code on the enclosed information card for claim purposes, then dispose of the receiver. You may still safely operate your fireplace or stove product manually by plugging it directly to the electrical outlet.

If you have had this concern corrected previously, you may be eligible for reimbursement of your cost for the repair. For more information regarding this recall contact (800) 348-7469.

In the event you choose to deliver your park model trailer for inspection, your dealer will complete a Skyline Repair Order. Upon completion of the inspection please sign the Skyline Repair Order and fill out the enclosed, self-addressed postage-paid Vehicle Information Update Card and return it to Skyline. If you feel confident you can make the inspection yourself, please fill out the self-addressed Vehicle Information Update Card, and return it to Skyline. Skyline will send a new replacement receiver for the affected receiver.

If You No Longer Own This Recreational Vehicle:

If you have changed your address or sold the travel trailer, please take a moment to provide the name and address of the person or dealership you sold it to on the enclosed Vehicle Information Update Card, and return it to Skyline. That way we can update our records, and notify the new owner using the information you provide.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you are unable to obtain the specified inspection and/or repair promptly and without charge, please contact (800) 733-4250.

If the repair facility fails or is unable to inspect this noncompliance without charge and within a reasonable time, please contact us at the number provided above so we can attempt to resolve the problem. You may also submit a written complaint to:

**Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington, D.C. 20590**

Your safety and satisfaction with your Skyline product are important to us and we regret any inconvenience to you.

Sincerely,

Skyline Corporation



Q.C. PASSED 1808

Date Code

Model Number

OR

DOC ID#

This style of recalled plug-in receivers have Model Numbers 47-1001 and 47-1010-R or DOC ID # 255K656-61-8367R



Handheld Transmitters

Dimplex FCC ID: ELY547-47-1010-R T40
 IC: 1492A-471010R 1MHz

Model No.: 47-1010-R
 Input: 120Vac, 60Hz, 15A OUTPUT: AC120V ~ 60Hz

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

CONFORMS TO UL STD. 60730-1A CERTIFIED TO CANICSA STD. E60730-1

CAUTION: FOR INDOOR USE ONLY.

Resistive Load	15A	Motor Load	1/3HP
Incandescent Lamp	300W	TV	400W

Cet appareil est conforme à la partie 15 des règles de la FCC. Le fonctionnement de cet appareil est soumis aux conditions suivantes: 1) Cet appareil ne doit pas causer d'interférence nuisible. 2) Cet appareil doit accepter toute interférence pouvant être reçue comprise l'interférence pouvant causer un fonctionnement non désiré.

Alimentation: 120 Vac, 60Hz, 15A Puissance: 120 Vac, 60Hz

ATTENTION: POUR USAGE À L'INTÉRIEUR SEULEMENT.

Charge résistive	15A	Charge du moteur	1/3HP
Lampe Incandescente	300W	Télév.	400W

Este dispositivo se conforma con la parte 15 de las reglas de la FCC. La operación de este dispositivo es sujeta las condiciones siguientes: 1) este dispositivo puede no causar interferencia dañina. 2) este dispositivo debe aceptar cualquier interferencia que se pueda recibir incluyendo interferencia que cause la operación indeseada.

Entrada: 120Vac, 60Hz, 15A Salida: 120Vac, 60Hz

PRECAUCIÓN: PARA EL USO DE INTERIOR SOLAMENTE.

La carga resistiva	15A		
1/3 HP motor carga	1/3HP		
Lámpara Incandescente	300W		
TV	400W		

Made in China / Fait en Chine / Hecho en China

ETL US 9700297

DOC ID 255K656-61-8367R

The device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following conditions: (1) This device may not cause harmful interference. (2) This device must accept any interference that may be received including interference that cause undesired operation.

CONFORME À 1500

CAUTION: FOR INDOOR USE ONLY

Resistive Load 15 A
 Motor Load 1/3 HP
 Incandescent Lamp 300 W
 TV 400 W

Cet appareil est conforme aux règlements 1500 de la FCC. Le fonctionnement de cet appareil est soumis aux conditions suivantes: 1) Cet appareil ne doit pas causer d'interférence nuisible. 2) Cet appareil doit accepter toute interférence pouvant être reçue y compris l'interférence pouvant causer un fonctionnement non désiré.

CONFORME À 1500

ATTENTION: POUR USAGE À L'INTÉRIEUR SEULEMENT

Charge résistive 15 A
 Charge du moteur 1/3 HP
 Lampe Incandescente 300 W
 Télé 400 W

Este dispositivo se conforma con la parte 15 de las reglas de la FCC. La operación de este dispositivo es sujeta las condiciones siguientes: 1) este dispositivo puede no causar interferencia dañina. 2) este dispositivo debe aceptar cualquier interferencia que se pueda recibir incluyendo interferencia que cause la operación indeseada.

Entrada: 120 Vac, 60 Hz, 15 A Salida: 120 Vac, 60 Hz

UL LISTED SA LISTED MADE IN CHINA

This style of recalled plug-in receiver has Model Number APT-1315



Model Number

MODEL NO: APT-1315
 FCC ID: JAY1M-1300N
 UL FILE NO: E121729
 THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION OF THIS DEVICE IS SUBJECT TO THE FOLLOWING CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRABLE OPERATION. MADE IN CHINA

DATE CODE: H5101

CODE: 239

Date Code