

July 2010

SAFETY RECALL NOTICE

CLUB CAR CARRYALL 2 LSV & CARRYALL 6 LSV

Dear Club Car Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Club Car has decided that Carryall 2 LSV and Carryall 6 LSV vehicles manufactured before June 10, 2010 fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 209 Seat Belt Assemblies.

The seat belt assemblies originally provided with your vehicle meet Society of Automotive Engineers (SAE) J2292 standard for seat belts. The difference in these standards is the impact level at which the seat belt retractor locks. The seat belt retractor locks at a higher impact level than required by the FMVSS 209. In a vehicle impact, a passenger may not be adequately restrained by the seat belt.

Club Car, in cooperation with the National Highway Traffic Safety Administration, has initiated a recall to replace the SAE J2292 seat belt with a FMVSS 209 seat belt. Please contact any authorized Club Car LSV dealer to arrange for the seat belt replacement. The dealer will replace the seat belt at no cost to you. This replacement should take less than one hour to complete. Your nearest dealer has been identified below. Additional dealers may be located on www.clubcar.com. The replacement parts will be available after July 15, 2010.

Our records indicate that you are the current owner of the vehicle listed below. If you are no longer in possession of this vehicle, please contact us at 1-800-227-0739 extension 3014 with any information you might have concerning the current location of the vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to lessee within 10 days.

If you believe that Club Car or Club Car's dealers have failed to remedy this non-compliance without charge in a reasonable time, you may submit a complaint to Club Car at the address above; or submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you had your seat belt replaced before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact us at 1-800-227-0739 extension 3014.

Vehicle Information Carryall 2 LSV VIN # - 5J5XXXXXXXXXXXXXXXXXX

Owner	Nearest Dealer
John Doe 123 Main St. Anytown USA 12345	Dealer Name 123 Main St Anytown, USA 12345