



MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

SAFETY RECALL NOTICE

2015 Center Square Road
Logan Township, NJ 08085
(856) 467-4500
(856) 467-4695 Fax

August 4, 2010

LOTERIA DE PUERTO RICO
139 AVE. CARLOS CHARDON
SAN JUAN PR 00918

IMPORTANT!

- ❖ Please be advised that your 2008-2010 Model Year FE83D, FE84D or FG84D truck referenced by VIN below is open for a safety recall related to antilock brake system (ABS) hydraulic unit harness.
- ❖ MFTA urges that you schedule an appointment with an Authorized Dealer or Parts and Service Center to perform the recall, at no charge to you, as soon as possible.
- ❖ Refer to this Recall Notification letter when speaking with Dealer Service Department personnel.

SAFETY RECALL NOTIFICATION – C1004210 – ABS Hydraulic Unit Harness
NHTSA SAFETY RECALL – 10V-319

Vehicle Identification Number – JL6BBD1S0AK000104

Dear Mitsubishi Fuso Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mitsubishi Fuso Truck of America, Inc. has decided that a defect which relates to motor vehicle safety exists in the ABS hydraulic unit harness ground circuit. On affected vehicles equipped with an anti-lock brake system, the ground wire is positioned in such a manner that water could enter the wire casing and travel to the ABS hydraulic unit connector. If water invasion occurs during normal vehicle operation, the connector terminals could become corroded. In the worst case, the corrosion could affect the hydraulic motor circuit in such a manner that the motor would operate continuously, causing the motor to overheat and start a fire without warning.

Continued on the back.

Please detach, sign & return this prepaid business reply postcard if any owner/vehicle information requires updating.



OWNER/VEHICLE INFORMATION CHANGE

If this vehicle is no longer in your possession, or the address has changed, please make any necessary changes and indicate the "REASON FOR CHANGE" in the check boxes provided. If you make changes, please sign and date, detach, and return this prepaid business reply postcard.

VIN: JL6BBD1S0AK000104

Owner of Record:
LOTERIA DE PUERTO RICO
139 AVE. CARLOS CHARDON
SAN JUAN PR 00918

Owner/Address Correction:

If you're searching for a Dealer or
Parts and Service Center in your area,
try the "Find a Dealer" link at:

www.mitfuso.com

REASON FOR CHANGE

- Truck Exported Truck Totalled Truck Scrapped/Out of Service
 Truck Stolen Truck Sold Owner Address Correction

Signature: _____ Date: ____ / ____ / ____

IMPORTANT! Sign and date this reply, as permanent changes are not valid without your signature.

The ABS hydraulic unit and chassis side hydraulic unit connector will be inspected for corrosion and/or damage. Affected components will be replaced. Then, a sub harness that replaces the ABS hydraulic unit ground wire circuit will be installed. The procedure will be completed at no cost to you when performed by an Authorized Dealer or Parts and Service Center. The scheduled time for repair is approximately 1.2 – 4.2 hours.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you are the lessor of the above referenced vehicle, please forward this notification immediately.

Note: If you have incurred costs to obtain a remedy for the problem addressed in this recall prior to initial notification, please present the paid invoice to an Authorized Mitsubishi Fuso Dealer or Parts and Service Center. The Dealer/Parts & Service Center will submit a warranty claim to MFTA on your behalf. Reimbursement of these costs should be expected within 30 days of warranty claim submittal.

We at MFTA regret any inconvenience this situation may cause you. However, your safety and continued satisfaction with our product are most important to us.


If your MFTA Dealer is unable to perform this procedure without charge, or within a reasonable amount of time, please contact MFTA Customer Service toll-free at 877-711-0707 for assistance. You may also contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

William P. Mohr
Director, Service Operations



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO 20 BERLIN NJ
POSTAGE WILL BE PAID BY ADDRESSEE

mitsubishi fuso
TRUCK OF AMERICA, INC.
117 JACKSON RD.
BERLIN, NJ 08009-9917





MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

2015 Center Square Road
Logan Township, NJ 08085
(856) 467-4500
(856) 467-4695 Fax

NOTIFICACIÓN DE RECAMBIO DE SEGURIDAD

4 de agosto de 2010

LOTERIA DE PUERTO RICO
139 AVE. CARLOS CHARDON
SAN JUAN PR 00918

¡IMPORTANTE!

- ❖ Le informamos que su camioneta FE83D, FE84d o FG84D modelo 2008-2010 con referencia al NIV a continuación está abierta para un recambio de seguridad relacionado con el arnés de la unidad hidráulica del sistema antibloqueo de frenos (ABS).
- ❖ La MFTA lo insta a programar una cita con un Distribuidor autorizado o Centro de servicio y refacciones para llevar a cabo un recambio, sin cargo a usted, tan pronto como sea posible.
- ❖ Refiérase a esta Notificación de Recambio cuando hable con el personal del Departamento de servicio del distribuidor.

**NOTIFICACIÓN DE RECAMBIO DE SEGURIDAD – C1004210 – Arnés de unidad hidráulica del ABS
RECAMBIO DE SEGURIDAD NHTSA – 10V-319**

Número de identificación vehicular – JL6BBD1S0AK000104

Estimado propietario de una camioneta Mitsubishi Fuso:

Se le envía esta notificación de acuerdo con los requerimientos de la Ley Nacional para la Seguridad de Tránsito y Vehículos Automotor.

Mitsubishi Fuso Truck of America, Inc. ha decidido que existe un defecto que se relaciona con la seguridad del vehículo automotor en el circuito de conexión a tierra del arnés de la unidad hidráulica del ABS. En los vehículos afectados equipados con un sistema de antibloqueo de frenos, el cable a tierra está colocado de tal manera que puede llegar a entrar agua en la cubierta del cable y viajar hasta el conector de la unidad hidráulica del ABS. Si

Si está buscando un Distribuidor o un Centro de servicio y refacciones en su área, intente con el enlace “**Buscar un distribuidor**” en:

www.mitfuso.com

ocurre una invasión durante el funcionamiento normal del vehículo, las terminales del conductor se pueden corroer. En el peor de los casos, la corrosión podría afectar el circuito del motor hidráulico de tal manera que el motor funcionaría continuamente, causando que el motor se sobrecaliente e inicie un fuego sin ninguna advertencia.

Se inspeccionarán la unidad hidráulica del ABS y el conector de la unidad hidráulica del lado del chasis por corrosión y/o daño. Los componentes afectados serán reemplazados. Luego, se instalará un subarnés que reemplaza el circuito del cable a tierra de la unidad hidráulica del ABS. El procedimiento se completará sin costo para usted si se lleva a cabo con un Distribuidor autorizado o en un Centro de servicio y refacciones. El tiempo programado para reparación es de aproximadamente 1.2 a 4.2 horas.

El reglamento federal requiere que cualquier arrendador de vehículo que reciba esta notificación debe pasar una copia de esta notificación al arrendatario antes de diez días. Si usted es el arrendador del vehículo antes mencionado, pase esta notificación inmediatamente.

Nota: Si ha incurrido en costos para obtener un remedio por el problema tratado en este recambio antes de la notificación inicial, presente la factura pagada en un Distribuidor autorizado de Mitsubishi Fuso o Centro de servicio y refacciones. El Distribuidor/Centro de servicio y refacciones presentará una reclamación de garantía a la MFTA en su nombre. Puede esperar el reembolso de estos costos antes de 30 días de presentada la reclamación de garantía.

Nosotros en MFTA lamentamos cualquier inconveniente que esta situación pueda causarle. Sin embargo, su seguridad y continua satisfacción con nuestro producto es lo más importante para nosotros.

Si su Distribuidor MFTA no puede llevar a cabo este procedimiento sin cargo, o dentro de un periodo de tiempo razonable, contacte al número sin costo 877-711-0707 de Servicio a cliente de MFTA por asistencia. También puede contactar al Administrador, la Administración Nacional de Seguridad de Tránsito en Carreteras, en 1200 New Jersey Avenue, SE., Washington, DC 20590; o llame a la Línea especial para seguridad de vehículos sin costo al 1-888-327-4236 (TTY: 1-800-424-9153); o vaya a <http://www.safercar.gov>.

Cordialmente,



William P. Mohr
Director de operaciones de servicio



MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

2015 Center Square Road
Logan Twp., NJ 08085

SAFETY RECALL NOTICE

LOTERIA DE PUERTO RICO
139 AVE. CARLOS CHARDON
SAN JUAN PR 00918
