

**HYUNDAI****TRANSLEAD**

8880 Rio San Diego Dr., Suite 600
San Diego CA 92108-1640
Tel: 619-574-1500 Fax: 619-542-0301

C O P Y

October 27, 2010

FedEx Freight

Attn: Mr. Allen Barrett

Warranty Manager

Delivery Code 2274

2200 Forward Drive

Harrison, AR 72601

Subject: Arvin Meritor Ride Sentry MPA Series Suspension Safety Campaign
Arvin Meritor ID Number: C10AB
NHTSA ID Number: 10V-506

Dear Mr. Barrett:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicles Safety Act.

Hyundai Translead has decided that a defect that relates to motor vehicle safety exists in certain 53' composite trailers that Hyundai Translead manufactured for FedEx Freight. These composite trailers were manufactured during May 2010.

ArvinMeritor reports that an unknown percentage of their Ride Sentry™ MPA Series Suspensions may have missing welds at the interface of the lower seat bracket and axle Beam, which could allow the axle to roll out of position and potentially impact trailer handling. Enclosure (1) contains a list of affected suspensions and corresponding trailer vehicle identification numbers (VINS) subject to the requirements of this campaign.


ArvinMeritor has published Technical Bulletin TP-10172 Enclosure (2) detailing inspection and repair procedures for affected suspensions. ArvinMeritor has stated that they will reimburse at the standard repair time (SRT) of one hour for vehicle inspection and up to one additional hour per axle seat requiring weld repair. Please note that claims may be processed by calling their OnTrac Customer Service Center at 866-668-7221 and following instructions on the enclosed Technical Bulletin.

FedEx Freight may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov> if FedEx Freight believes that the manufacturer has failed or is unable to remedy the defect or noncompliance without charge.

The ArvinMeritor campaign has been reported to NHTSA and inspection findings and repairs are required to be reported in accordance with 49 CFR Part 573. Hyundai Translead will provide additional information regarding this reporting in future communications.

The Hyundai Translead POC for this campaign is Vincent R. Vold, Senior Manager Warranty, [T] 619.680.3144, [F] 619.209.5621 or [Email] vincentv@translead.com . Please contact him directly with any questions you may have.

Sincerely,



Martin Forsyth
Director of Warranty

Cc: Vincent Vold

Enclosures: (1) List of Affected VIN's and corresponding suspension serial numbers.
(2) ArvinMeritor Technical Bulletin, TP-10172