



Navistar, Inc.
4201 Winfield Road
Warrenville, IL 60555 USA

navistar.com



A NAVISTAR COMPANY

SAFETY RECALL G-10518

JANUARY 2011

Dear INTERNATIONAL® Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Navistar has decided that a defect which relates to motor vehicle safety exists in certain 4300 and 4400 model trucks built 2/25/10 thru 9/20/10 with a MaxxForce DT engine.

REASON FOR THIS RECALL

The engine turbo oil supply line may rub on the frame rail possibly causing an oil leak in the engine compartment.

RISK TO MOTOR VEHICLE SAFETY

An oil leak in the engine compartment may cause a fire possibly resulting in property damage, personal injury, or death.

DEFECT REMEDY

The repair will involve replacement of the engine turbo oil supply line. Dealers have parts and instructions to repair the affected vehicles. The repair will be performed free of charge and take approximately 2 hours to complete.

ACTIONS YOU SHOULD TAKE

Navistar's records indicate that you own a vehicle involved in this recall. The vehicle is identified on the enclosed card.

If you own this vehicle, please schedule an appointment with any INTERNATIONAL® dealer to have your vehicle repaired. You can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.internationaltrucks.com>.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

IF YOU NEED FURTHER ASSISTANCE

If you believe that Navistar has failed to remedy the defect without charge or within a reasonable time, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9152); or go to <http://www.safercar.gov>.

Navistar requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

Navistar, Inc.



IC Bus, LLC
4201 Winfield Road
Warrenville, IL 60555 USA

navistar.com

A NAVISTAR COMPANY

SAFETY RECALL G-10518

JANUARY 2011

Dear IC Bus Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that a defect which relates to motor vehicle safety exists in certain CE and HC commercial model buses built 2/25/10 thru 9/20/10 with a MaxxFer DT engine.

REASON FOR THIS RECALL

The engine turbo oil supply line may rub on the frame rail possibly causing an oil leak in the engine compartment.

RISK TO MOTOR VEHICLE SAFETY

The engine turbo oil supply line may rub on the frame rail possibly causing an oil leak in the engine compartment.

DEFECT REMEDY

The repair will involve replacement of the engine turbo oil supply line. Dealers have parts and instructions to repair the affected vehicles. The repair will be performed free of charge and take approximately 2 hours to complete.

ACTIONS YOU SHOULD TAKE

IC Bus' records indicate that you own a vehicle involved in this recall. The vehicle is identified on the enclosed card.

If you own this vehicle, please schedule an appointment with any IC Bus dealer to have your vehicle repaired. You can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.icbus.com>.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

IF YOU NEED ASSISTANCE

If you believe that IC Bus has failed to remedy the defect without charge or within a reasonable time, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9152); or go to <http://www.safercar.gov>.

IC Bus requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

IC Bus, LLC