



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Telephone: 714-372-6000
www.mitsubishicars.com

July 13, 2011

Jennifer Timian
Chief, Recall Management Division
National Highway Traffic Safety Administration
1200 New Jersey Ave. SE
Washington, D.C. 20590

Subject: Quarterly Campaign Progress Report – 2nd Quarter 2011

Dear Ms. Timian:

Attached is the Quarterly Campaign Progress Report prepared in accordance with 49 CFR Part 573.7 for the calendar quarter April 1 through June 30, 2011 (2nd Quarter 2011).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

A handwritten signature in black ink that reads "Sharon Kaplan".

Sharon Kaplan
Sr. Specialist, Technical Compliance
Mitsubishi Motors North America, Inc.
Telephone: (714) 372-6148
Fax: (714) 934-4202
E-mail: skkaplan@mmsa.com

cc: Kelly Schuler (Email)

Enclosure



MMNA 2nd Quarter 2011
Safety Recall Campaign Progress Report

| NHTSA Recall Number | MMNA Recall Number | Campaign Name | Owner Notification Start | Owner Notification End | Total Number of Vehicles Involved | Number Vehicles Inspected and Repaired | Number Vehicles inspected and not needing Repair | Vehicles Exported | Vehicles Stolen | Vehicles Scrapped | Notification Undeliverable | Sold or Traded | Quarters Reported |
|---------------------|----------------------------------|--|--------------------------|------------------------|-----------------------------------|--|--|-------------------|-----------------|-------------------|----------------------------|----------------|-------------------|
| 10V066 | SR-10-001 | 2010 Galant A/T Oil Cooler Pipe | 22-Mar-10 | 22-Mar-10 | 2,307 | 690 | 1,393 | 0 | 0 | 0 | 6 | 1 | 5 |
| 10V065 | SR-10-002 | 2004 Endeavor Fuel Filler Pipe | 6-Jul-10 | 6-Jul-10 | 35,456 | | | | | | | | |
| 10V514 | SR-10-003 | 2006-2008 Endeavor HVAC Controller Replacement | 7-Dec-10 | 7-Dec-10 | 19,402 | 7,774 | NA | 0 | 0 | 63 | 415 | 6 | 3 |
| 10V065 (expanded) | SR-11-001 (supercedes SR-10-002) | 2004-2010 Endeavor Fuel Filler Pipe | 28-Feb-11 | 28-Feb-11 | 64,441 | 17,390 * | NA | 6 | 0 | 260 | 1,890 | 56 | 2 |

SR-10-002 was superseded by SR-11-001, which expands the affected model years.

* 3,213 anti-corrosion coating & protector installation + 14,177 pipe replacements