



**Mitsubishi Motors North America, Inc.**

6400 Katella Avenue  
Cypress, CA 90630  
Telephone: 714-372-6000  
www.mitsubishicars.com

July 13, 2011

Jennifer Timian  
Chief, Recall Management Division  
National Highway Traffic Safety Administration  
1200 New Jersey Ave. SE  
Washington, D.C. 20590

Subject: Quarterly Campaign Progress Report – 2nd Quarter 2011

Dear Ms. Timian:

Attached is the Quarterly Campaign Progress Report prepared in accordance with 49 CFR Part 573.7 for the calendar quarter April 1 through June 30, 2011 (2nd Quarter 2011).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

A handwritten signature in black ink that reads "Sharon Kaplan".

Sharon Kaplan  
Sr. Specialist, Technical Compliance  
Mitsubishi Motors North America, Inc.  
Telephone: (714) 372-6148  
Fax: (714) 934-4202  
E-mail: [skkaplan@mmsa.com](mailto:skkaplan@mmsa.com)

cc: Kelly Schuler (Email)

Enclosure



MMNA 2nd Quarter 2011  
Safety Recall Campaign Progress Report

| NHTSA Recall Number | MMNA Recall Number               | Campaign Name                                  | Owner Notification Start | Owner Notification End | Total Number of Vehicles Involved | Number Vehicles Inspected and Repaired | Number Vehicles Inspected and not needing Repair | Vehicles Exported | Vehicles Stolen | Vehicles Scrapped | Notification Undeliverable | Sold or Traded | Quarters Reported |
|---------------------|----------------------------------|--|--------------------------|------------------------|-----------------------------------|--|--|-------------------|-----------------|-------------------|----------------------------|----------------|-------------------|
| 10V066              | SR-10-001                        | 2010 Galant A/T Oil Cooler Pipe                | 22-Mar-10                | 22-Mar-10              | 2,307                             | 690                                    | 1,393  | 0                 | 0               | 0                 | 6                          | 1              | 5                 |
| 10V065              | SR-10-002                        | 2004 Endeavor Fuel Filler Pipe                 | 6-Jul-10                 | 6-Jul-10               | 35,456                            |  |  |                   |                 |                   |                            |                |                   |
| 10V514              | SR-10-003                        | 2006-2008 Endeavor HVAC Controller Replacement | 7-Dec-10                 | 7-Dec-10               | 19,402                            | 7,774                                  | NA   | 0                 | 0               | 63                | 415                        | 6              | 3                 |
| 10V065 (expanded)   | SR-11-001 (supercedes SR-10-002) | 2004-2010 Endeavor Fuel Filler Pipe            | 28-Feb-11                | 28-Feb-11              | 64,441                            | 17,390 *                               | NA   | 6                 | 0               | 260               | 1,890                      | 56             | 2                 |

SR-10-002 was superseded by SR-11-001, which expands the affected model years.

\* 3,213 anti-corrosion coating & protector installation + 14,177 pipe replacements