

Parking Brake Lever

Models: All Models
Part Number: 0111-03597
Description: Parking Brake Lever

Bulletin Number: 09A1003
NHTSA Recall Number: 10V-080
Date: February 22, 2010

Service Bulletin

Subject: Parking Brake Lever assembly replacement.

Affected VIN range: 050597 thru 050739

Problem: An issue has been identified with the Parking Brake Lever assembly that can render the parking brake system inoperative.

Solution: The Park Brake Lever must be replaced with an appropriate replacement lever. If the Park Brake Lever has failed it will need to be replaced.

Procedure:

- 1.) **BEFORE ATTEMPTING SERVICE, TURN THE MASTER DISCONNECT SWITCH (MDS), LOCATED IN THE ACCESS PANEL OF THE LOWER DASH, TO THE 'OFF' POSITION. (See Owner's Manual)**
- 2.) Gain access to the Park Brake Lever. (See Service Manual, Section 4 – BRAKES). Access will vary depending on Coupe or Sedan Model vehicle.
- 3.) Follow written procedure(s) in Model Year Specific Service Manual.




Photo 1 - Park Brake Lever (Coupe Models)




Photo 2 - Park Brake Lever (Sedan Models)

Time

Reimbursements: Labor Code BRK-01-07 Coupe 0.3 hrs
Labor Code BRK-01-08 Sedan 0.4 hrs

Special Notes: To ALL Service providers; Please be absolutely sure to inspect every vehicle identified by Vehicle Identification Number noted above for this application. Every Park Brake Lever should be replaced per these instructions. It is MANDATORY to return the old lever, by supplied Return Tag, once this bulletin is completed.