



THIS DOCUMENT AND THE CONTENTS DISCUSSED HEREIN ARE THE CONFIDENTIAL AND PROPRIETARY INFORMATION OF NEW FLYER INDUSTRIES CANADA ULC AND NEW FLYER OF AMERICA INC. AND ARE DISCLOSED BY NEW FLYER IN CONFIDENCE. THIS DOCUMENT AND THE CONTENTS HEREIN ARE NOT TO BE DISCLOSED BY THE INTENDED RECIPIENT WITHOUT THE PRIOR WRITTEN AUTHORIZATION OF NEW FLYER. ANY UNAUTHORIZED DISCLOSURE, REPRODUCTION OR OTHER DISTRIBUTION OF THIS DOCUMENT OR INFORMATION IS STRICTLY PROHIBITED AND MAY RESULT IN ACTION BEING TAKEN AGAINST THE PARTY MAKING THE UNAUTHORIZED DISCLOSURE. THIS DOCUMENT AND ALL COPIES HEREOF MUST BE RETURNED TO NEW FLYER UPON REQUEST.

INSTRUCTION TO SERVICE ITS: 4274

SECTION: 450 Flooring	MODEL: <input type="checkbox"/> 30FT <input type="checkbox"/> 35FT <input checked="" type="checkbox"/> 40FT <input type="checkbox"/> 60FT <input checked="" type="checkbox"/> DSL <input type="checkbox"/> CNG <input type="checkbox"/> LNG <input type="checkbox"/> ELEC	TYPE: <input type="checkbox"/> HIGH FLOOR <input checked="" type="checkbox"/> LOW FLOOR	WRITTEN BY: Jermie Marasigan
---------------------------------	---	---	---------------------------------

OBJECTIVE/SUBJECT:
Remove and replace driveshaft access door.

- PROCEDURE:**
1. Turn the main battery disconnect switch to the "OFF" position.
 2. Locate the driveshaft access door on the rear interior of the coach.
 3. Remove the existing driveshaft access door assembly. Discard the old door.
 4. Install the newly supplied driveshaft access door with honeycomb material NF P/N: 405471.
- NOTE:** Ensure that the door latch is properly secured once installed.




Figure 1: Enter Description of Figure Here

5. Turn the main battery disconnect switch to the "ON" position.



LABOUR ESTIMATE				
	Operation	Men	Hours	Labour Time M X HR
1	Remove and replace driveshaft access door.	1	0.25	0.25

PARTS REQUIRED					
Item	Part Number	Description	Qty. per Coach	Units	Notes
1	405471	ASSY-DRIVESHAFT DOOR AUSTIN	1	EA	

SPECIAL TOOLS REQUIRED					
Item	Part Number	Description	Qty. per Coach	Unit of Measure	Notes
		No special tools required			