

Keystone RV Company

SERVICE ADVISORY # 10-139

Residence Washer / Dryer Circuit

It has been determined that some vehicles may have been built with an incorrect rated circuit breaker. This service advisory will explain how to correct the situation.

Models Included: 2010-2011 Residence Travel Trailers

Serial Number Range: 2010; AW160308 – AW160332, 2011; BW160000 – BW160017

Parts Required per Unit: - (1) KRV # 113705 Breaker - 120v - 1P - 20A/20A

Tools required: - #2 Phillips screw driver - #2 Straight screw driver

INSTRUCTIONS

ONE: PREPARING THE TRAILER

- Step 1.** Locate the trailer on a level, flat, and hard surface. Chock the wheels.
- Step 2.** Disconnect the shore cord and negative lead from the battery.

TWO: REMOVE AND REPLACE BREAKER

- Step 1.** Remove front cover from the breaker panel. Remove the 30/20 circuit breaker marked washer and dryer. See figure 1. Install a 20/20 breaker in the washer / dryer position. Replace the front cover on the breaker panel.



Remove breaker
Labeled
Washer / dryer

Fig.1

- Step 2.** Reconnect the unit power. Perform hot skin test.

WARRANTY REIMBURSEMENT

Submit the claim on Key Express or on a Keystone Warranty claim form with **Service Advisory # 10-139** and **Flat Rate Code # 7113942B** noted in the customer complaint section of the form. The amount of time authorized for this repair is 0.3 hours.

If you have any questions, please call Keystone RV Customer Service at **(866) 273-1454**