

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

January 26, 2012

Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215, Rm. W45-206)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

**Re: Defect Information Report – Supplemental Report No. 4
10V-112 (10C-2, FL-575), S60 EPA07 MCM Reprogramming in Fire Truck
Applications – Second Notice
Owner Re-notification**

Ms. Lewis,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and a representative copy of the document distributed to owners.

(c)(3) Owners of 9, vehicles were notified on January 23, 2011.

(c) (10) A copy of communications sent to owners is attached.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Amy Martin, CAL-OSHA
Enclosure



Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, Michigan 48239-4001
Telephone: 313-592-5000

DATE
NHTSA # 10V-112

Owner Name
Address
City, State Zip Code

SECOND NOTICE

Safety Recall 10C2
Series 60 EPA07 MCM Reprogramming in Fire Truck Applications

This notice is sent to you in accordance with requirement of the National Traffic and Motor Vehicle Safety Act. This notice is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Detroit Diesel has decided that a defect which relates to motor vehicle safety exists in certain Series 60 EPA07 engines equipped in Fire Truck Applications.

Certain Series 60 EPA07 engines will require reprogramming of the Motor Control Module (MCM) with **v62.6.0.0** software (*or higher*) and fuel map version ZGS 114 (*or higher*). Reprogramming the MCM may prevent unexpected engine shutdown under certain conditions which could hamper rescue operations and place the public at risk.

Records available to us indicate that your vehicle is equipped with one of these affected engines. Detroit Diesel will repair your engine at no charge to you.

We ask that you take your unit to the closest Authorized Repair Facility to have the work performed. We estimate that the labor time required to perform this Safety Recall on your engine is approximately 1.0 hour.

If you have any questions about this Safety Recall you may call our Customer Support Center at (313) 592-5800. If you believe that Detroit Diesel has failed or is unable to remedy the defect without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or to <http://www.safercar.gov>. If your vehicle is involved in the Canadian portion, you may wish to notify Transport Canada, ASFAD, Place de Ville Tower C, 330 Sparks Street, Ottawa, ON K1A 0N5, or phone (800) 333-0510.



Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, Michigan 48239-4001
Telephone: 313-592-5000

If you had this repair done before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. **If you are the lessor of this vehicle, Federal Law requires that you forward this notice to the lessee within ten days.** For more information, contact Customer Support Center at Detroit Diesel Corporation, 13400 Outer Drive West, Detroit, MI 48239 or call (800) 445-1980.

We regret any inconvenience this action may cause. However, we have taken this action in the interest of your continued satisfaction with our products as well as our interest in motor vehicle safety.

**DETROIT DIESEL
SAFETY RECALL 10C2
SERVICE ADMINISTRATION CAMPAIGN COORDINATOR (BX-5)**