



NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37067

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.3111

November 23, 2011

Mr. Ric Willard
Acting Chief, Recall Management Division
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave, S.E.
Washington, D.C. 20590

Dear Mr. Willard,

In accordance with the renotification request received in our office on November 8, 2011 we are transmitting the enclosed owner renotification letters for the following safety recall campaigns:

<u>NHTSA Number</u>	<u>Recall Name</u>
10V-312	Pathfinder QX4 Passenger Air Bag Inflator
10V-349	Armada QX56 A-Pillar Finisher
10V-175	G35 Coupe and Sedan Belt Tension Sensor
10V-372	Frontier KC Front Passenger Seat Tether Anchor
10V-074	Frontier Xterra Pathfinder Fuel Gauge Inaccuracy
10V-075	Titan Armada QX56 Fuel Gauge Inaccuracy


Nissan will conduct the owner renotification in accordance with the guidelines listed in the letter. The letters meet the requirements of 49 CFR Part 577.10, "Follow-up Notification" and include a "Johnson Box" highlighting the pertinent information for owners. Nissan searched current state motor vehicle registration records on November 11, 2011 in order to update the original owner list for the aforementioned recall campaigns. The revised owner list will be available on December 2, 2011 and owner renotification will commence according to the schedule below:

NHTSA Number	Owner Notification Begins	Owner Notification Ends
10V-312	February 6, 2012	February 6, 2012
10V-349	February 6, 2012	February 6, 2012
10V-175	January 20, 2012	March 5, 2012
10V-372	February 6, 2012	February 6, 2012
10V-074	February 6, 2012	February 6, 2012
10V-075	January 9, 2012	January 23, 2012

In addition, all of the aforementioned recalls will be reported for the next three quarters as required by the renotification request.

Should you have any questions, please contact Will Swindell at 615-725-5527.

Regards,

A handwritten signature in cursive script that reads "John Gibbons".

John Gibbons
Senior Manager, Technical Compliance
Nissan North America, Inc.

Attachments-9



NISSAN NORTH AMERICA, INC.

National Headquarters
Consumer Affairs Department

P.O. Box 685003
Franklin, Tennessee 37068-5003

RECALL 10V-175

FOLLOW-UP NOTIFICATION

Dear Infiniti G35 Owner:

IMPORTANT

- Your 2005-2006 model year Infiniti G35 sedan or 2005-2007 model year Infiniti G35 coupe is involved in a safety recall because the passenger air bag may shut off.
- **Please schedule an appointment with your Nissan dealer.**
- **This service will be performed for you at no charge.**

This second notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Infiniti has decided that a defect which relates to motor vehicle safety exists in some 2005-2006 model year G35 sedan and 2005-2007 model year G35 coupe vehicles. Our records indicate that you own or lease the Infiniti vehicle identified by the VIN shown below.

Reason for Recall

On some of the potentially affected vehicles, the passenger air bag harness connector under the front passenger seat can develop additional electrical resistance due to wear caused by movement within the connector. This resistance could cause the passenger air bag to shut off.

If this occurs, the **RED** air bag warning light will come on and the front passenger air bag will not work. In addition, the amber front passenger air bag status light would illuminate together with the above mentioned red air bag light to alert the vehicle operator that the passenger air bag is not operating. Driving with a non-working passenger air bag could increase the front passenger's risk of injury in a collision.

What Infiniti Will Do

To address this potential passenger air bag issue, your Infiniti dealer will repair the passenger air bag harness located under the seat. This free service should take about two hours to complete, but your Infiniti dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

If you have not done so already, we urge you to please contact your Infiniti dealer at your earliest convenience in order to arrange an appointment to have your vehicle inspected and repaired.

NOTE:

- If a **RED** air bag warning light located in your instrument cluster illuminates together with the **YELLOW** "Pass Air Bag Off" status light (located in the center display next to the clock) and stays on for longer than a few seconds, the passenger airbag in your vehicle will not operate. You should take your car to an Infiniti dealer for repair as soon as possible, and you should not let anyone ride in the front passenger seat until the dealer has repaired your vehicle.

- If a **YELLOW** "Pass Air Bag Off" status light (located in the center display next to the clock) illuminates, but the **RED** air bag warning light does not, this is normal and does not mean that the passenger air bag is malfunctioning (see your Owners Manual). However, you should still bring your vehicle for inspection and repair at your earliest convenience.

Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Infiniti dealer.

If you have previously paid to have your passenger air bag harness repaired prior to this campaign, you may be eligible for reimbursement of the related expense. Please contact the National Consumer Affairs Department, Infiniti Division, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-662-6200. You may also contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.