

## VOLKSWAGEN

GROUP OF AMERICA

Mr. Daniel Smith  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Attention: Recall Management Division (NVS-215)  
1200 New Jersey Avenue, S.E.  
Washington, DC 20590

CHRIS SANDVIG NAME  
GENERAL MANAGER COMPLIANCE/TREAD TITLE  
PRODUCT COMPLIANCE DEPARTMENT  
248-754-5000 PHONE  
248-754-5093 FAX  
MAY 10, 2011 DATE

Subject: Amendment to Voluntary Recall 11V-151  
2010 Model Year Volkswagen Routan  
Replacement of WIN Module (Ignition Switch)

Dear Mr. Smith:

This will amend our Part 573 report dated March 01, 2011 by providing the following updated information:

VOLKSWAGEN GROUP OF AMERICA, INC.  
3800 HAMLIN ROAD  
AUBURN HILLS, MI 48326  
PHONE +1 248 754 5000

573.6 (c) (2) **Identification of Vehicles**

Make : Volkswagen

Line : Routan

Model Year : 2010

Month/Year  
of Manufacture : October 2009 – July 2010

VIN Numbers  
of Affected Vehicles: 2V4RW\_D\_AR138355 – 2V4RW\_D\_AR360513

Other Identification : None

573.6 (c) (3) **Number of Vehicles Potentially Containing the Defect**

Approximately 12,744 vehicles are affected by this recall in the United States.

573.6 (c) (8) **Proposed Remedial Program**

Due to a parts supply issue, mailing dates are anticipated as follows:

Dealers: on or about June 7, 2011

Customers: on or about June 7, 2011

Sincerely,



Christopher T. Sandvig  
General Manager Compliance/TREAD  
Service & Quality