

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Responsibility and Reports¹

On JUNE 10, 2011, ECLIPSE RECREATIONAL VEHICLES decided that (a defect which relates to motor vehicle safety)(a noncompliance with Federal Motor Vehicle Safety Standard No. _____) exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports.

Date this report was prepared: 7/19/2011

Furnish the manufacturer's identification code for this recall (if applicable): SG-18CK-22CK

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

ECLIPSE RECREATIONAL VEHICLES INC.

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.


DANNY ZACARIAS – SERVICE MANAGER

Telephone Number: 951-684-6868 X14

Fax No.: 951-684-4449

Name and Title of Person who prepared this report DANNY ZACARIAS

Signed:



¹ Each manufacturer must furnish a report, to the Associate Administrator for Enforcement, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Responsibility and Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. George Person at (202) 366-5210, by FAX at (202) 366-7882, or by E-Mail to RMD.ODI@dot.gov.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

Make(s): MILAN Model Years Involved: 2011 & 2012 Model(s): TL18CK & TL22CK

Production Dates: Beginning: 12/20/2010 Ending: 02/11/2011

VIN Range: Beginning: 61004 Ending: 61050

Vehicle Type: TRAVEL TRAILER Bodystyle: TRAVEL TRAILER

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

TL18CK & TL22CK BUILT WITH 14" TIRES

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Vehicles equipped with certain items of equipment from January 1, 1996 through April 1, 1997, then what was the percentage of the recalled Vehicles of all Vehicles manufactured during that time period.

98 %

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Model	Year	Number of Vehicles Potentially Involved
MILAN TL18CK	2011	10
MILAN TL22CK	2011	10
MILAN TL18CK	2012	10
MILAN TL22CK	2012	10

Total Number Potentially Affected by the Recall: 40

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance: 98%

Identify and describe how the recall population was determined--in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

MILAN TL18CK & MILAN TL22CK UNITS PRODUCED FROM 12/20/10 THRU 2/11/2011 WITH 14" TIRES.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

UNITS PRODUCED WITH 14" TIRES, TIRE PACKARD LABEL READS 15" TIRES

Describe the cause(s) of the defect or noncompliance condition.

UNITS PRODUCED WITH 14" TIRES, TIRE PACKARD LABEL READS 15" TIRES

Describe the consequence(s) of the defect or noncompliance condition.

NONE

NEED TO HAVE THE TIRE PACKARD LABEL REPLACED

Identify any warning which can (a) precede or (b) occur.

NONE

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

NONE

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

N/A

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

- 6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.
- 7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

UNITS PRODUCED WITH 14" TIRES, TIRE PACKARD LABEL READS 15" TIRES
NEED TO REPLACE THE TIRE PACKARD LABEL WITH CORRECT LABEL

V. Identify the Remedy

8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

NEW LABELS WILL BE MAILED TO THE CONSUMER, DEALER IF NOT SOLD, AND WILL BE
INSTRUCTED TO PLACE OVER THE EXISTING TIRE PACKARD LABEL.

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

NEW LABELS WILL BE MAILED TO THE CONSUMER, DEALER IF NOT SOLD, AND WILL BE INSTRUCTED TO PLACE OVER THE EXISTING TIRE PACKARD LABEL.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

NEW LABELS WILL BE MAILED TO THE CONSUMER, DEALER IF NOT SOLD, AND WILL BE INSTRUCTED TO PLACE OVER THE EXISTING TIRE PACKARD LABEL.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

THE USE OF 14" TIRES WAS DISCONTINUED

VI. Identify the Recall Schedule

10. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

ALL NEW LABELS WILL BE MAILED BY 7/29/2011

VII. Furnish Recall Communications

11. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the

time your company determines the defect or noncompliance condition on, not just the initial notification. A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) or by E-Mail to RMD.ODI@dot.gov for review prior to mailing.

Note that these documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.