

Safety Defect and Noncompliance Report Guide for Vehicles Part 573 Defect and Noncompliance Report¹

In September, 2011 Altec Industries Inc decided that a condition which relates to motor vehicle safety exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports.

Date this report was prepared: **December 15, 2011**

Furnish the manufacturer's identification code for this recall (if applicable): **CSN 554**

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Altec Industries, Inc

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

Joshua T. Chard
Director, Corporate and Product Safety

Telephone Number: **205-408-8627** Fax No.: **205-981-3733**

Name and Title of Person who prepared this report.

Philip D. Purdy
Manager, Media

Signed: _____

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, *for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:*

Make(s): Altec Model Years Involved: 2008 - 2011 Model(s): N/A
Production Dates: Beginning: N/A Ending: N/A

VIN Range: Beginning: N/A Ending: N/A

Vehicle Type: N/A Body style: N/A

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

This recall affects Altec products utilizing model 1314 or 1315 Sure Power Battery Separator Devices.

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

<u>Model</u>	<u>Year</u>	<u>Number of Vehicles Potentially Involved</u>
Aerial Device/Digger Derrick	2008 - 2011	245

Total Number Potentially Affected by the Recall: 245

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance: **100% to be inspected but percent of vehicles with the defective component is unknown.**

Identify and describe how the recall population was determined – in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

The recall population was determined by reviewing production and quality records to identify products using the model 1314 or 1315 Sure Power Battery Separator Device.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

Describe the cause(s) of the defect or noncompliance condition.

The battery separator could have a defective component.

Describe the consequence(s) of the defect or noncompliance condition.

The battery separator could overheat and possibly cause a fire.

Identify any warning which can (a) precede or (b) occur.

N/A

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

Cooper Bussmann
114 Old State Road
Ellisville, MO 63021-5942
636-394-2877

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier.

Name: Joshua Bennett

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

In September 2011 Altec became aware that Sure Power, Inc. issued a recall of certain models of battery separators. Altec does not record Battery Separators by their model or serial number. Altec began a diligent search based on purchase orders, delivery

dates and production records in an effort to identify products that could potentially have been manufactured with the recalled components. There have been no reported accidents or injuries.

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

N/A

V. Identify the Remedy

8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

Altec will issue a recall letter (CSN 554) to owners of all potentially affected units.

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

All affected battery separators will be replaced.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

N/A

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

Sure Power, Inc. is providing improved battery separators.

VI. Identify the Recall Schedule

- 10.** Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

Submitted with this report is a draft of Altec's CSN 554. Once CSN 554 has been approved and returned, Altec will immediately mail it to the customers affected. There are no dealers/retailers affected.