

SAFETY RECALL – P7405 Baldwin Oil Filters

Dear P7405 Baldwin Oil Filter owners,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Baldwin Filters has determined that a defect which relates to motor vehicle safety exists in certain P7405 filters manufactured between November 2009 and November 2010. These filters might fail due to an apparent problem with the media and adhesive used in filter. This can lead to loss of engine power and eventual engine failure. It is at least possible that under certain circumstances a sudden loss of engine power while in operation could increase the risk of a crash. The filters seem particularly prone to malfunction in cold weather conditions.

WHAT WE WILL DO

We will replace the P7405 filter with the original equipment filter. The replacement will be without charge to you.

WHAT YOU SHOULD DO

If you suspect you have a filter described above, please contact your local Detroit Diesel service provider as soon as possible to arrange a service date and so that the replacement original equipment filter can be ordered if necessary. If you have any problem obtaining the needed repair, please contact Baldwin Filters Service Engineering at (800) 822-5394 Ext. 79729. After contacting your local Detroit Diesel service provider and the Baldwin Filters service engineering group, if you are still not able to have the safety defect remedied without charge and within a reasonable time, you may wish to write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington, DC 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

If prior to this notification, you replaced a P7405 filter to deal with the defect described above or had repairs performed on your engine as a result of a defective P7405 filter, please contact Baldwin Filters Service Engineering at (800) 822-5394 Ext. 79729. Baldwin Filters will reimburse you for the cost of the filter replacement or engine repair upon receipt of the appropriate documentation. With respect to replacement of filters, documentation demonstrating that you owned a P7405 filter and a receipt demonstrating that you had a new filter installed after the purchase of the P7405 filter will be required. With respect to reimbursement for engine repairs, documentation demonstrating that you owned a P7405 filter and a receipt indicating that repairs addressed problems caused by the defective filter will be required.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

4400 East Highway 30

P.O. Box 6010

Kearney, NE 68848-6010

Ph. 800-822-5394

FAX 800-828-4453

Internet www.baldwinfilter.com

TS 16949
ISO 9001



QUALITY SYSTEM
CERTIFIED

BALDWIN FILTERS 
a CLARCOR company

4400 East Highway 30
P.O. Box 6010
Kearney, Nebraska 68848-6010

SAFETY RECALL NOTICE

C R England
Attn: Mr. Craig Green
4701 West 2100 South
Salt Lake City UT 84120