



The slack adjusters potentially involved are Gunitite brand automatic slack adjusters bearing the following lot numbers and identification codes:

**Lot Numbers and Corresponding Mold Line Nomenclature**

Lot Nos.	Mold Line	Lot Nos.	Mold Line	Lot Nos.	Mold Line	Lot Nos.	Mold Line
OK06	1H	OK02	1H	1A18	1H	OK20	H
OK07	1H	OK04	1H	1A21	1H		
OK14	1H	OK10	1H	1A22	1H		
OK16	1H	OK12	1H				
OK17	1H	OK18	1H				
OK18	1H	OK22	1H				
OK19	1H	OK24	1H				
OK20	1H	OL12	1H				
OK28	1H	OL16	1H				
OK30	1H	OL22	1H				
OK37	1H	OL24	1H				
		OL28	1H				
		OL30	1H				

The lot number and mold line nomenclature are cast into the housing on each slack adjuster and can be found on the inside of the slack adjuster close to the outside flange. See attached Gunitite Service Advisory.

If you have difficulty identifying the date stamping on the slack adjusters or have any questions or to report on slack adjusters involved you may contact Gunitite at 1-855-857-8645 between 7:00 a.m. and 4:00 p.m. Central time, Monday through Friday.

Defected slack adjuster(s) should be shipped to Gunitite 302 Peoples Avenue, Rockford, IL 66104; Attention Field Engineering. Be sure to include your name, address and telephone number with any slack adjuster(s) returned to Gunitite. It is recommended you contact Gunitite before shipment to ensure the slack adjuster is properly identified for handling. All slack adjusters containing the matching lot numbers and identified for handling. All slack adjusters containing the matching lot numbers and mold line identifiers will be replaced free of charge to you. Slack adjusters sent to Gunitite for inspections that are not included in the inspection campaign will be returned to you. Gunitite will reimburse you for shipping costs involved in returning product with matching lot numbers and mold line identifiers. Any customer who has incurred cost for repair of their vehicle or slack adjuster due to the above described defect prior to notification may also be entitled to reimbursement.

If, after contacting Gunita and/or returning a slack adjuster subject to this product inspection campaign, you are not able to have a slack adjusters subject to this product inspection campaign replaced without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Gunita is sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with Gunita slack adjusters.

Best Regards, Dennis Rosa  
Rosa Trailer Mfg.  
PH: 715-478-3435  
Fax: 715-478-1860