

[Next Unread Message](#)[View Message](#)

Sent on 10 27 2011 Expires on 11 27 2011
From Motorcycle Service Communications
Subject STOP SALE NOTICE: 2010 NT700V



Motorcycle Service

October 27, 2011

Dear Honda Motorcycle Dealer,

Honda is launching a SAFETY RECALL on a limited number of 2010 model year NT700V motorcycles to replace the tire information label on the swingarm. Units within the affected VIN range may bear a Tire Information Label that displays incorrect tire size and inflation information. Improper inflation of tires may affect vehicle handling and lead to premature tire failure, thereby increasing the risk of a crash. Effective immediately, **you must not sell** a NT700V within the affected VIN range without first performing the recall repair procedure.

AFFECTED UNITS:**2010 NT700V**

VTMRC522*AE001443 thru VTMRC522*AE001562

(*) denotes check digit

On or before October 28, every dealer with affected units will receive a Fed Ex envelope containing replacement tire information labels and a copy of the Service Bulletin that details inspection and, if necessary, replacement procedures, as well as warranty information.

As soon as the Tire Information Label is replaced, please submit a warranty claim to indicate that your dealership has completed the recall action in compliance with Federal Law and your AHM Sales and Service Agreement. If you have any questions about your obligations, please refer to this link:

[Sales Bulletin #10-0290, Recall Compliance Letter](#)

Please ensure all departments at your dealership are aware of this safety recall action.

Thank you for your cooperation.
American Honda Motor Co., Inc.
Motorcycle Division

Bulletin Number 11-0464

[▲ BACK TO TOP](#)