 <b>HYUNDAI</b> NEW THINKING. NEW POSSIBILITIES.	GROUP <b>CAMPAIGN</b>	NUMBER <b>11-01-015</b>
	DATE <b>MAY, 2011</b>	MODEL(S) <b>2010 TUCSON (LM)</b>
<b>Technical Service Bulletin</b>		
<b>SUBJECT TUCSON (LM) REAR REFLECTOR REPLACEMENT (CAMPAIGN 101)</b>		

**\* IMPORTANT**


**\*\*\* Dealer Stock and Retail Vehicles \*\*\***

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been completed. Dealers must also complete all open recalls on used vehicles, demo and rental vehicles prior to placing them in customer use.

Dealers must perform this campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the service department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open campaigns.

**Description:** This bulletin provides information related to a recall on some 2010 MY TUCSON (LM) vehicles to replace the rear reflectors. The reflecting performance of rear reflectors may decrease by improper rear reflector lens.



**Applicable Vehicles:** From Feb. 27, 2010 to Apr. 17, 2010

**Parts Information:**

PART NAME	BEFORE	AFTER	QTY
Rear reflector	92405-2S100 (LH) 92406-2S100 (RH)	92405-2S100QQH (Kit contains LH & RH)	1

**Warranty Information:**

OP CODE	OPERATION	OP TIME
10C017R0	Rear reflector replacement	0.6 M/H


NOTE: Submit Claim on Campaign Claim Entry Screen

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair


**Service Procedure:**

1. Verify that the vehicle has an open Recall 101 by accessing the "Warranty Vehicle Information" in WEBDCS.


Locate the rear reflectors.



2. Remove the rear combination lamp mounting screws (LH/RH).




3. Push/pull the rear combination lamp rearward and remove it (LH/RH).




**CAUTION**

**Be careful not to damage the rear combination lamp and paint.**

- 4. Disconnect the rear combination lamp connector and remove the rear combination lamp (LH/RH).




- 5. Remove the rear bumper upper screw and clips (LH/RH).



- 6. Remove the rear bumper cover mounting screw and clips (LH/RH).



7. Remove the bumper mounting bolts (LH/RH).




8. Pull out the rear bumper end portion (LH/RH).



**CAUTION**


**Be careful not to damage the bumper.**

9. Pull the bumper gently rearward and place it on clean fabric.




**CAUTION**  
Be careful to not damage the guide pin when removing bumper.


10. Remove the rear bumper rail by removing 5 fasteners.



11. Remove the screw from the reflector on each side (LH/RH).



12. Remove the reflectors by squeezing the clip.



13. Pull the rear reflectors out of the rear bumper (LH/RH).



14. Install new reflectors (LH/RH).  
92405-2S100QQH

Reinstall all other removed components in reverse order of their removal.

