

POSTED ON ISIS

FEB 23 2012

SERVICE PROCEDURE

Compliance Dept.

G-11522
FEBRUARY 2012

SUBJECT:

SAFETY RECALL

MAILED

FEB 28 2012

ELECTRONIC STABILITY CONTROL on certain
ProStar® model trucks built 3/22/11 thru 12/9/11
with feature code 04AZX – Meritor WABCO
electronic stability control.

Compliance Dept.

DEFECT DESCRIPTION

The electronic stability control system may incorrectly perceive an over steer situation under certain unique road conditions involving tight, successive, highly banked curves in opposite directions, and may apply individual front wheel brakes when system intervention is not necessary. If the driver is slow to react during this incorrect electronic stability control system intervention, the vehicle may deviate from the intended line of travel possibly increasing the risk of a crash.

MODELS INVOLVED

This Safety Recall involves certain ProStar® model trucks built 3/22/11 thru 12/9/11 with feature code 04AZX – Meritor WABCO electronic stability control.

PARTS INFORMATION

Part Number	Part Description	Quantity
FRK1110118	Kit, SR11522 WABCO ESC	1

SERVICE PROCEDURE

WARNING! PARK VEHICLE ON HARD FLAT SURFACE, TURN THE ENGINE OFF, SET THE PARKING BRAKE, AND BLOCK THE WHEELS TO PREVENT THE VEHICLE FROM MOVING IN BOTH DIRECTIONS. FAILURE TO DO SO MAY RESULT IN PROPERTY DAMAGE, PERSONAL INJURY, AND/OR DEATH.

WARNING! IF THE VEHICLE MUST BE RAISED, DO NOT WORK UNDER THE VEHICLE SUPPORTED ONLY BY JACKS. JACKS CAN SLIP OR FALL OVER, POTENTIALLY RESULTING IN PROPERTY DAMAGE, PERSONAL INJURY AND/OR DEATH.

WARNING! ALWAYS WEAR SAFE EYE PROTECTION WHEN PERFORMING VEHICLE MAINTENANCE. FAILURE TO DO SO MAY RESULT IN SERIOUS EYE INJURY.

1. Replace the vehicle's electronic stability control module and calibrate it per Meritor-Wabco's Technical Bulletin TP-1205. A copy of TP-1205 is at the end of this service procedure and can be downloaded at meritorwabco.com.

If you have any questions regarding the material covered in TP-1205, please contact OnTrac Customer Service at 866-668-7221 or visit meritorwabco.com.

END OF SERVICE PROCEDURE

LABOR INFORMATION

Operation Number	Description	Time
A40-11522-1	R&R and Calibrate ESC Module	1.5

CAMPAIGN IDENTIFICATION LABEL

Each vehicle corrected in accordance with this campaign must be marked with a CTS-1075 Campaign Identification Label.

Complete the label and attach on a clean surface next to the Vehicle Identification Number (VIN) plate.



ADMINISTRATIVE/DEALER RESPONSIBILITIES

WARRANTY CLAIMS

Refer to Dealer Warranty Manual for procedures to conduct Recall Campaigns.

It is important that the Recall Coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Manual, Section 7-1. Special attention should be given to Items 39 through 44.

GROUP	NOUN	C	WARR.	TP	PAD
Enter number G-					
Leave blank					
C (CAUSE) Enter either 1, 2, 3. (see below)					
1. Inspected (No repair required).					
2. Inspected and repaired.					
3. Defective part from parts stock.					
WARRANTY (Warranty Code) Enter 40.					
TYPE PART Enter P for type part causing failure.					
PAD Enter 100					

UNITED STATES AND POSSESSIONS

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle that is subject to a vehicle recall campaign must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after a tender of a vehicle is *prima facie* evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within 60 days, the owner may be entitled to replacement with an identical or reasonable equivalent vehicle at no charge, or to a refund of the purchase price less a reasonable allowance for depreciation.

Dealers must correct all vehicles subject to this campaign at no charge to the owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

Dealers should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer, or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your dealer location.

Dealers must make every effort to promptly schedule an appointment with each owner to repair his or her vehicle as soon as possible. However, consistent with the customer notification, dealers are expected to complete the repairs on the mutually agreed upon service date.

Dealers involved in the recall process will be furnished a listing of owner names and addresses to enable them to follow up with owners and have the vehicles corrected. Use of this listing must be limited to this campaign because the list may contain information obtained from state motor vehicle registration records and the use of such motor vehicle registration data for purposes other than this campaign is a violation of law in several states.

CANADA

Dealers must correct all vehicles subject to this campaign at no charge to the owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

Dealers should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer, or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your dealer location.

Dealers must make every effort to promptly schedule an appointment with each owner to repair his or her vehicle as soon as possible. However, consistent with the customer notification, dealers are expected to complete the repairs on the mutually agreed upon service date.

Dealers involved in the recall process will be furnished a listing of owner names and addresses to enable them to follow up with owners and have the vehicles corrected. Use of this listing must be limited to this campaign because the list may contain information obtained from state motor vehicle registration records and the use of such motor vehicle registration data for purposes other than this campaign is a violation of law in several states.

EXPORT

Export Distributors should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer, or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your distributor location.

Export Distributors are to submit warranty claims in the usual manner making reference to this recall number.

Export Distributors are expected to provide full cooperation and follow-up with respect to this important subject matter. If you have any questions or need further assistance, please contact the Regional Service Manager at your regional office.

NAVISTAR, INC

MERITOR WABCO

Technical Bulletin

Replacement of the ESC3 Module with the ESC5 Module on Vehicles Equipped with Electronic Stability Control (ESC) and the Calibration Procedure

Affected Part Numbers: 446 065 020 0, 446 065 027 0, 440 850 179 0, 400 850 185 0, 400 850 195 0

Hazard Alert Messages

Read and observe all Warning and Caution hazard alert messages in this publication. They provide information that can help prevent serious personal injury, damage to components, or both.

How to Obtain Additional Maintenance and Service Information

If you have any questions regarding the material covered in this bulletin, or for information about the Meritor WABCO product line, please contact the OnTrac Customer Service Center at 866-OnTrac (668-7221) or visit our website: meritorwabco.com

Description and Function

The ESC module is part of the ESC system. It measures the vehicle yaw rate as well as vehicle lateral acceleration. The ESC module includes part of the ESC control algorithm. It exchanges data with the ESC ABS ECU via the ESC system internal data link. The ABS ECU supplies the module with power and ground.

Field Repair Kit Part Number FRK11-101-18

The ESC Module field kit, part number FRK11-101-18, is required for completing the replacement and calibration procedure. The kit consists of the following parts.

- ESC5 Module Kit, part number 400 850 199 0
- Technical Bulletin TP-1205

NOTE: This replacement procedure consists of several different steps based on the type of ECU that the vehicle uses. Please carefully review the following instruction first before proceeding.

Identifying the Type of ECU in the Vehicle

1. Connect your laptop or PC to the vehicle.
2. Launch the Meritor WABCO TOOLBOX® Diagnostic Software and click on the Pneumatic ABS Icon for Truck, Tractor and Buses. Figure 1.




Figure 1

3. In the main ABS ECU screen, locate the field for the ECU software version. Figure 2.




Figure 2

4. Once the ECU revision is located, please review the following table and use the applicable procedure.

Software Rev.	Procedure to Use
E435, E436, E440, E441	Use the procedures on page 2.
E404	Use the procedures on page 4.
E401	Please contact the OnTrac Customer Service Center at 866-OnTrac1 (668-7221).

Procedures for ECUs with Software Revision E435, E436, E440 or E441

Step 1 — Obtaining the Special Version of TOOLBOX® Software

In order to complete the Calibration Procedure for the ESC5 Module, a special version of the Meritor WABCO TOOLBOX® Diagnostic Software is required.

To obtain this special version, you will need an internet connection to perform the following.

1. Type this link in Windows Explorer:
<ftp://ftp.mwtoolbox.com/>
2. When prompted, use:
 - ID >> ESC5
 - Password >> ESC5Module (case sensitive)
3. Go into the folder called TOOLBOX ESC5 Update.
4. Select all files in the folder and copy them into a specific folder in your laptop hard drive.
5. Double click on the file "Setup.exe".

Step 2 — Saving the Steering Ratios

1. Connect your laptop or PC to the vehicle.
2. Launch the Meritor WABCO TOOLBOX® Diagnostic Software and click on the Pneumatic ABS Icon for Truck, Tractor and Buses. Figure 1.
3. On the main ECU screen, select from the top bar click on "ESC Menu". Figure 3.




Figure 3

4. Click on "ESC5 Update" Steering Ratios.

On the lower left corner of the main screen, you should see the following screen. Figure 4.





Figure 4

Once the system completes the process, the following message will be displayed. Figure 5.



5. Turn the ignition OFF.

Step 3 — Removing the ESC3 Module

Tools — To complete this procedure, you will need a wrench or a ratchet appropriate for the type of capscrews used to attach the ESC Module (ESC3) to the frame cross member.

WARNING

To prevent serious eye injury, always wear safe eye protection when you perform vehicle maintenance or service.

Park the vehicle on a level surface. Block the wheels to prevent the vehicle from moving. Support the vehicle with safety stands. Do not work under a vehicle supported only by jacks. Jacks can slip and fall over. Serious personal injury and damage to components can result.

1. Park the vehicle on a level surface with the steering wheel centered and the front wheels positioned straight ahead.
2. Turn the ignition switch to the OFF position and apply the parking brake.
3. Block the wheels to prevent the vehicle from moving.
4. If necessary, raise the vehicle off the ground and place safety stands under the vehicle.
5. Disconnect the wiring harness connector from the ESC Module.
6. Remove the two mounting capscrews and nuts. Remove the ESC Module. Figure 6.




Figure 6

Step 4 — Installing the New ESC5 Module

NOTE: It is important that the module is aligned correctly and the tab on the ESC module mounting surface fits into the appropriate hole.

1. Install the new ESC5 module included in the kit with the two capscrews and nuts. Tighten the capscrews per the manufacturer's recommendation.

(10579)
Printed in USA

2. Connect the wiring harness connector to the ESC Module. Hand-tighten only.

3. Remove the stands and blocks.

Step 5 — Calibrating the ESC System Straight Driving Portion

1. Turn the Ignition ON.
2. On the main screen, select "ESC Menu" and select "End of Line". Figure 7.




Figure 7

3. Click on "ESC Initialization". Figure 8.




Figure 8

TP-1205
Issued 12-11
Page 3

4. Check the message box. Figure 9.



Figure 9

5. Press the space bar or click "Continue" when ready to proceed.
 6. Carefully follow the instruction from the message box.

The Stability Light will start blinking when the 15 mph speed has been reached.

When straight driving is completed after about 800 feet, the Stability Light will stop blinking and will be ON solid.

NOTE: The Straight driving can be done in segments and the ECU will accumulate the information until the 800 feet are reached, but it must be done in the same Ignition cycle.

Step 6 — Testing the ESC System

When the ESC Calibration Procedure is completed, the ABS and ATC/ESC lamps should come on and go back off when ignition power is turned on. The ATC/ESC lamp may remain on briefly after the ABS lamp goes off.

There should not be any active faults displayed in the ECU memory.

Step 7 — Disposing of Removed Parts

Meritor WABCO requires that the ESC module removed from the vehicle be destroyed and disposed. The recommended method for destruction of the ESC Module is to drill a steel bit through the electric connector.

Procedures for ECUs with Software Revision E404

Step 1 — Removing the ESC3 Module

Tools — To complete this procedure, you will need a wrench or a ratchet appropriate for the type of capscrews used to attach the ESC Module (ESC3) to the frame cross member.

⚠ WARNING

To prevent serious eye injury, always wear safe eye protection when you perform vehicle maintenance or service.

Park the vehicle on a level surface. Block the wheels to prevent the vehicle from moving. Support the vehicle with safety stands. Do not work under a vehicle supported only by jacks. Jacks can slip and fall over. Serious personal injury and damage to components can result.

1. Park the vehicle on a level surface with the steering wheel centered and the front wheels positioned straight ahead.
2. Turn the ignition switch to the OFF position and apply the parking brake.
3. Block the wheels to prevent the vehicle from moving.
4. If necessary, raise the vehicle off the ground and place safety stands under the vehicle.
5. Disconnect the wiring harness connector from the ESC Module.
6. Remove the two mounting capscrews and nuts. Remove the ESC Module. Figure 10.




Figure 10


Step 2 — Installing the New ESC5 Module

NOTE: It is important that the module is aligned correctly and the tab on the ESC module mounting surface fits into the appropriate hole.


1. Install the new ESC5 module included in the kit with the two capscrews and nuts. Tighten the capscrews per the manufacturer's recommendation.
2. Connect the wiring harness connector to the ESC Module. Hand-tighten only.
3. Remove the stands and blocks.

Step 3 — Calibrating the ESC System Straight Driving Portion

1. Connect your laptop or PC to the vehicle.
2. On the main Screen, click "ESC Menu" and select "End-Of-Line". Figure 11.



3. Click on "ESC Initialization". Figure 12.



4. Check the message box. Figure 13.



5. Press the space bar or click "Continue" when ready to proceed.
6. Carefully follow the instruction from the message box.

The Stability Light will start blinking when the 15 mph speed has been reached.

When straight driving is completed after about 800 feet, the Stability Light will stop blinking and will be ON solid.

NOTE: The Straight driving can be done in segments and the ECU will accumulate the information until the 800 feet are reached, but it must be done in the same ignition cycle.

Step 4 — Calibrating the ESC System Steering Ratio Portion

1. After completing the Straight Driving Portion, the next message will appear. Carefully read the message box and follow the instructions. Figure 14.




Figure 14

2. Turn the steering wheel 360 degrees in either direction and begin driving.

NOTE: The Circle driving may also be done in segments and the ECU will accumulate the information until the desired distance is reached, but it must be done in the same ignition cycle.

The ATC/Stability Light will start blinking when the required conditions are met. Keep driving until the light turns off. Figure 15.




Figure 15

3. Stop the vehicle. Turn the steering wheel 360 degrees in the opposite direction and repeat the driving conditions.

Again, the Stability Light will start blinking when the required conditions are met. Keep driving until the light turns off. Figure 16.




Figure 16

4. A Message box with the Steering Ratio and Steering Angle Offset values will appear. Click "Close". Figure 17.




Figure 17

5. Read the message box and follow the instructions very carefully. Click "Close" and Cycle the Ignition. Figure 18.




Figure 18

MERITOR WABCO

Meritor WABCO Vehicle Control Systems
2135 West Maple Road
Troy, MI 48084-7121 USA
866-OnTrac1 (668-7221)
meritorwabco.com

Information contained in this publication was in effect at the time the publication was approved for printing and is subject to change without notice or liability. Meritor WABCO reserves the right to revise the information presented or to discontinue the production of parts described at any time.

Copyright 2011
Meritor, Inc.
All Rights Reserved

Printed in USA

TP-1205
Issued 12-11
(16579)