

U.S. Department of Transportation

National Highway Traffic Safety Administration

September 13, 2012

1200 New Jersey Avenue SE Washington, DC 20590

Mr. Adam Kopstein Volvo Cars of N.A., LLC 1 Volvo Drive Rockleigh, NJ 07647 NVS-215ET 12V-439

Subject: Defective SRS Control Unit-All cars quarantined

Dear Mr. Kopstein:

This letter serves to acknowledge Volvo Cars of N.A., LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

VOLVO/S60/2013 VOLVO/XC60/2013

Mfr's Report Date: September 10, 2012

NHTSA Campaign Number: 12V-439

Components:

AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Potential Number of Units Affected: 9

Problem Description:

Volvo is recalling certain model year 2013 S60 and XC60 vehicles. A manufacturing defect within the Supplemental Restraint System (SRS) control unit may lead to an inadvertent deployment of the seat belt pretensioner and/or inflatable curtain.

Consequence:

If the seat belt pretensioner and/or inflatable side curtain deploy without cause, the driver could be distracted and the driver's visibility could be reduced, increasing the risk of a crash.

Remedy:

These vehicles have not been sold and the SRS control unit will be replaced prior to the cars being sold. Owners may contact Volvo at 1-800-458-1552.

Notes:

The Volvo recall campaign number is 257. Consumers may also contact the National Highway Traffic Safety Administration's vehicle safety hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please submit one quarterly report identifying a 100% completion rate once all nine vehicles have been remedied.

Your contact for this recall will be Edison Thompson who may be reached by phone at 202-366-9525, or by email at edison.thompson@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

