



25161 Leer Dr
Elkhart, IN 46514

NHTSA Recall No. 12V-199
Transport Canada Recall No. – 2012-151

Safety Recall Notice

GC II[®], Pacer[®], Pacer LS[®], Pacer LTD[®], G Force[®], and Sentinel[®]

Dear Dealer:

This **Safety Recall Notice** is sent to you in accordance with the requirements of the United States National Traffic and Motor Vehicle Safety Act and The Canadian Motor Vehicle Safety Act and is important for your safety.

Goshen Coach decided that a defect which relates to motor vehicle safety exists in certain *GC II, Pacer LS, Pacer LTD, Pacer II, Sentinel, G-Force buses* manufactured between January 2007 and May 2011 that have Braun Corporation wheelchair lifts installed.

The Braun Corporation has decided that certain (series AA through DA) Century and Vista 2nd generation Dual Parallel Arm model wheelchair lifts manufactured from November, 2006 to September, 2010) may develop or exhibit a defect related to the outer rollstop latch. This defect may result in a passenger falling from the elevated lift platform and being injured or killed.

The required action is to replace the outer roll stop latch.

Please find attached a copy of the retail notification letter as well as the required repair procedure for this recall. If you have any problems or questions, please contact The Braun Customer Experience Group at 1-800-488-0359. A Braun Product Support representative will arrange for prompt attention to your lift.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of safety and continued satisfaction with our buses.

Sincerely,

Fred Schimmel
Standards and Compliance Manager

Re: NHTSA Recall No. – 12V-199
Transport Canada Recall No.- 2012-151