

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
Export Distributors
Direct Warranty Customers – U.S. and Canada

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090 FAX 503-745-9009

If you have questions about this Letter, please submit your inquiry on the Web at:

[AccessFreightliner.com / Support / My Tickets and Submit an Inquiry](http://AccessFreightliner.com/Support/MyTicketsandSubmitanInquiry)

REF #: ICI13-001

Effective: 2/05/2013

Release: 2/06/2013

SUBJECT: FL631 – Revised Bulletin

This letter is to inform you that a revised bulletin for Recall FL631, *Perpendicular Aluminum Air Tank Mounting Brackets*, has been posted on AccessFreightliner.com. Please print and use the revised bulletin for all work under FL631 from this point forward.

REVISIONS: Some vehicles in FL631A have two suspect brackets (p/n 12-22981-000) instead of only one. A second procedure has been added to FL631A for these vehicles. A typographical error in the SRTs in the Labor Allowance table has been corrected. A description of the suspect bracket has been added to the work instructions.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through [www.AccessFreightliner.com / Support / My Tickets and Submit an Inquiry](http://www.AccessFreightliner.com/Support/MyTicketsandSubmitanInquiry) from 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.