

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** Delivery Stop: 2013 M5, M6 Coupe and M6 Convertible Oil Pump  
**Date:** Friday, September 21, 2012 11:42:07 AM

Publish Date: September 21, 2012  
From: Technical Service  
Expiration Date: October 04, 2012

DCSnet Message  
Urgent



Subject: **Delivery Stop: 2013 M5, M6 Coupe and M6 Convertible Oil Pump**

BMW Dealer Principals, Sales Managers, Service Managers, and Parts Managers

A Delivery Stop has been issued by BMW AG to correct a potential problem with the engine oil pump on certain S63TU-equipped vehicles. Affected vehicles are the 2013 Model Year M5, M6 Coupe, and M6 Convertible. Vehicles equipped with an affected pump could experience a sudden loss of oil pressure which will result in severe engine damage.

BMW Customer Relations is contacting customers that have already taken delivery and recommending customers not drive the vehicle. A Q&A will be provided to all BMW dealers in the form of an additional DCS message later today. This Q&A will provide you with the necessary information to answer your customers' concerns.

Vehicles included in the accompanying VIN list must **not** be delivered until the repairs are completed.

**Do not order any parts at this time.**

Sincerely,

Technical Service

Attachments: [Delivery\\_Stop\\_VINS\[80ec98e2\].pdf](#)   
[Delivery\\_Stop\\_VINS\[80ec98e2\].pdf](#)

Recipients: BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All  
BMW Passenger Cars, All Offerings, All Regions, All Areas, Sales, All  
BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, All