

SAFETY RECALL-OUTER ROLLSTOP BARRIER LATCH
ON BRAUN CENTURY AND VISTA 2ND GENERATION PARALLEL
ARM LIFTS

Dear

Century II Series, Serial #DA-01932

NHTSA RECALL IDENTIFICATION NUMBER: 12E002

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Act.

The Braun Corporation has decided that certain (series AA through DA) Century and Vista 2nd generation Dual Parallel Arm model wheelchair lifts manufactured from November, 2006 to September, 2010) may develop or exhibit a defect related to the outer rollstop latch. This defect may result in a passenger falling from the elevated lift platform and being injured or killed.

Your lift, identified above, is affected. To correct this condition, please contact your local authorized Braun Dealer and schedule an appointment. The work will take less than one hour to complete, but additional time may be required depending on your inspection and their shop schedule.

Please bring this Owner Notification Form with you at the time of your appointment and give it to the dealer. This form identifies the lift and the service required. If you have any problem obtaining the needed repair, please contact The Braun Customer Experience Group at 1-800-488-0359.

We regret any inconvenience that action may cause you, but we are concerned for your safety.

Thank you for your attention to this important matter,

Marla J. Meyers
Prime-Time Specialty Vehicles