



*SUZUKI MOTOR OF AMERICA, INC.*

## **IMPORTANT SAFETY RECALL NOTIFICATION**

Dear Suzuki Owner:

Update

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Suzuki Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2007 Suzuki XL7 vehicles originally sold or currently registered in the high temperature states of Arizona, California, Nevada and Texas. According to our records, you own one of the vehicles subject to this recall. The recall designator code is NZ.

The subject vehicles have a condition where the plastic supply or return port on the fuel pump module may crack, which could cause a fuel leak. The driver may notice a fuel odor while the vehicle is being driven or after it is parked. If the crack becomes large enough, fuel may be observed dripping onto the ground and vehicle performance may be affected. If an ignition source were present, a fire could occur.

To correct this condition when parts are available, your Suzuki dealer will replace the fuel pump module at no cost to you for parts and labor.

Replacement parts continue not to be currently available but we are working as quickly as possible to correct the parts availability situation. Suzuki will send a third letter when parts are available.

When you receive a confirming letter informing you that recall parts are available, please contact your Suzuki dealer to schedule an appointment for this Important Safety Recall.

We sincerely regret any inconvenience that this important safety recall may cause, but we are certain you understand our interest in your continued satisfaction with your Suzuki vehicle.

Sincerely,

SUZUKI  
Automotive Service and Quality