

# Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date 2013-07-19

Date in (yyyy-mm-dd) format

Reporting Quarter Q2 2013

Report Author Dominique Gagnon  
 Phone 418-831-5432 x 235  
 E-mail [dominique.gagnon@volvo.com](mailto:dominique.gagnon@volvo.com)

NHTSA Recall #	Prevoist Recall #	Description	Manufacturer	Date notification to purchasers began	Date notification to purchasers was completed	Safety Recall Quarterly Report ...		Total Number of Vehicles/Pces of Equipment Involved			Total Number Inspected & Remedied			Completion (%), per country			Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For internal use only: Nb of years reporting the recall...	Comments		
						From...	Through...	USA	Canada	Total	USA	Canada	Total	USA	Canada	Total						
1	9E-35	SR09-10	INSP. & REPL. DRAG LINK TIE ROD END	n/a	2009-06-30	Renotification to customers on 2012-12-20	2009-06-30	2013-06-30	17	7	24	0	2	2	0	29	8	0	0	4.1	Recall applicable to parts sold in After-Market	
2	11V-135	SR11-10	REPLACEMENT FUEL TANK SUPPORT	Prevost	2011-04-12	2011-04-12	2011-04-12	2013-06-30	39	10	49	38	10	48	97	100	98	0	0	2.3		
3	11V-364	SR11-52	FUSEBOX CONNECTIONS-INSPECT AND TORQUE TIGHTEN	Volvo Bus	2011-07-20	2011-07-20	2011-07-20	2013-06-30	179	n/a	179	164	0	164	92	n/a	92	0	0	2.0		
4	12V-303	SR12-16	ACCELERATOR PEDAL THROTTLE POSITION SENSOR REPLACEMENT (former wb10-33)	Prevost	2012-07-13	2012-07-13	2012-07-13	2013-06-30	260	142	402	251	142	393	97	100	98	0	0	1.0	Vehicles repaired under former warranty bulletin WB10-33 are included	
5	12V-304	SR12-17	Tag Axle Hub Cap Screw Replacement	Prevost	n/a	n/a	2012-07-05	2013-06-30	2	n/a	2	2		2	100	n/a	100	0	0	1.0		
6	12V-300	SR12-19	Steering Gearbox Bolts	Prevost	2012-08-02	2012-08-02	2012-08-02	2013-06-30	20	31	51	16	28	44	80	90	86	0	0	0.9		
7	12V-309	SR12-20	Automatic Fire Detection and Suppression System (AFSS) – Rerouting Linear Thermal Detector (LTD)	Prevost	2012-07-18	2012-07-18	2012-07-18	2013-06-30	84	18	102	77	17	94	92	94	92	0	0	1.0	Vehicles repaired under former warranty bulletin WB09-16 are included	
8	12V-315	SR12-24	PROPER RUBBING PROTECTION FOR THE JUMP-STARTING POSITIVE TERMINAL BLOCK CABLE	Prevost	2012-07-17	2012-07-17	2012-07-17	2013-06-30	256	172	428	198	107	305	77	62	71	0	0	1.0	Vehicles repaired under former warranty bulletin WB10-04 are included	
9	12V-325	SR12-25	Front Suspension Torqueing	Prevost	2012-07-06	2012-07-06	2012-07-06	2013-06-30	8	n/a	8	8		8	100	n/a	100	0	0	1.0		
10	12V-337	SR12-26	Power Cable Protection	Prevost	2012-08-13	2012-08-13	2012-08-13	2013-06-30	211	80	291	132	69	201	63	86	69	0	0	0.9		
11	12V-435	SR12-29	AUTOMATIC FIRE DETECTION AND SUPPRESSION SYSTEM (AFSS) – PROTECTION OF LINEAR THERMAL DETECTOR (LTD)	Prevost	2012-09-27	2012-09-27	2012-09-27	2013-06-30	15	n/a	15	11		11	73	n/a	73	0	0	0.8		
12	12V-511	SR12-39	Power Cable Rubbing	Prevost	2012-11-14	2012-11-14	2012-11-14	2013-06-30	51	40	91	38	33	71	75	83	78	0	0	0.6		
13	12V-564	SR12-47	AFSS Cylinder Relocation	Prevost	2012-12-19	2012-12-19	2012-12-19	2013-06-30	79	10	89	75	10	85	95	100	96	0	0	0.5		
14	12V-205	SR12-57	Emergency Windows - wheel chair lift vehicles	Volvo Bus	2012-09-26	2012-09-26	2012-09-26	2013-06-30	27	n/a	27	14	n/a	14	52	n/a	52	0	0	0.8		
15	12V-295	SR12-59	Bodywork SW Update	Volvo Bus	2012-07-13	2012-07-13	2012-07-13	2013-06-30	9	n/a	9	9	n/a	9	100	n/a	100	0	0	1.0		
16	12V-313	SR12-61	PASSENGER SEAT TRACK INSPECTION AND REPAIR	Volvo Bus	2012-09-24	2012-09-24	2012-09-24	2013-06-30	145	n/a	145	78	n/a	78	54	n/a	54	0	0	0.8		
17	12V-450	SR12-65	Hose protection for hydraulic pressure pipe	Volvo Bus	2012-10-22	2012-10-22	2012-10-22	2013-06-30	246	n/a	246	155	n/a	155	63	n/a	63	0	0	0.7		
18	12V-539	SR12-69	WCL Safety Pins	Volvo Bus	2013-01-31	2013-02-05	2013-01-31	2013-06-30	53	n/a	53	24	n/a	24	45	n/a	45	0	0	0.4		
19	12V-600	SR13-01	Radius Rod Support	Prevost	2013-01-28	2013-01-28	2013-01-28	2013-06-30	158	37	195	69	22	91	44	59	47	0	0	0.4		
20	13V-015	SR13-03	AFSS Linear Thermal Detector Replacement	Prevost	2013-03-19 (epa us10)	2013-06-11 (epa us07)	2013-03-19	2013-06-30	438	68	506	244	30	274	56	44	54	0	0	0.3		
21	13V-021	SR13-05	NEW SIDE MARKERS WITH NON-REFLECT.	Prevost	2013-02-05	2013-02-05	2013-02-05	2013-06-30	43	16	59	18	10	28	42	63	47	0	0	0.4		
22	13V-039	SR13-07	ECU SOFT UPDATE L-H IDLE PARAMET	Prevost	2013-05-02	2013-05-02	2013-05-02	2013-06-30	1019	418	1437	460	195	655	45	47	46	0	200	0.2		
23	13V-055	SR13-08	DRAGLINK TURNBUCKLE INSP. & REPL	Prevost	2013-05-02	2013-05-02	2013-05-02	2013-06-30	1441	472	1913	344	178	522	24	38	27			0.2		
24	13V-150	SR13-26	EMERGENCY EXIT SEQUENCE ON AWNING WINDOW DECALS	Prevost	n/a, recall canceled																This recall is cancelled	
25	13E-022	SR13-31	MGM Type 24 J-series piston parking brake chamber	n/a	TBC																Recall applicable to parts sold in After-Market	
26	13v-278	SR13-53	Tail Lamp Photometrics	Prevost	Expected Aug. 28 2013																	
27	13V-171	SR13-80	Mod. of Engine Speed Parameters for Limp Home Mode -Volvo D13 Engine ECU, SW Update	Volvo Bus	2013-07-02	2013-07-02	2013-07-02					281	n/a	281	100		100	36	n/a	36	0	Completion to be part of Q3 2013 report