

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.7

Report Date Oct 2 2012, revised Oct 31 2012
Reporting Quarter Q3 2012

Date in (yyyy-mm-dd) format

Report Author Dominique Gagnon
Phone 418-831-5432 x 235
E-mail dominique.gagnon@volvo.com

								Safety Recall Quarterly Report ...		Total Number of Vehicles/Pces of Equipment Involved			Total Number Inspected & Remedied			Completion (%), per country			Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For internal use only: Nb of years reporting the recall...	Comments
	NHTSA Recall Number	Canada DOT recall Number	Prevost Recall #	Description	Manufacturer	Date notification to purchasers began	Date notification to purchasers was completed	From...	Through...	USA	Canada	Total	USA	Canada	Total	USA	Canada	Total				
1	11V-135	2011-089	SR11-10	REPLACEMENT FUEL TANK SUPPORT	Prevost	2011-04-12	2011-04-12	2011-04-12	2012-09-30	39	10	49	34	9	43	87	90	88	0	0	1.5	
2	12V-303	2012-191	SR12-16	ACCELERATOR PEDAL THROTTLE POSITION SENSOR REPLACEMENT (former wb10-33)	Prevost	2012-07-13	2012-07-13	2012-07-13	2012-09-30	11 261	3 141	14 402	1 251	1 139	2 390	96	99	97	0	0	0.2	Oct 31 2012: vehicles repaired under former warranty bulletin WB10-33 are now included
3	12V-304	n/a	SR12-17	Tag Axle Hub Cap Screw Replacement	Prevost	n/a	n/a	2012-07-05	2012-09-30	2	0	2	2	0	2	100	n/a	100	0	0	0.2	This would be the first and last time that this recall is reported
4	12V-300	2012-200	SR12-19	Steering Gearbox Bolts	Prevost	2012-08-02	2012-08-02	2012-08-02	2012-09-30	21	31	52			0	0	0	0	0	0	0.2	
5	12V-309	2012-203	SR12-20	Automatic Fire Detection and Suppression System (AFSS) – Rerouting Linear Thermal Detector (LTD)	Prevost	2012-07-18	2012-07-18	2012-07-18	2012-09-30	16 85	8 17	24 102	2 72	1 13	3 85	85	76	83	0	0	0.2	Oct 31 2012 : vehicles repaired under former warranty bulletin WB09-16 are now included
6	12V-315	2012-204	SR12-24	PROPER RUBBING PROTECTION FOR THE JUMP-STARTING POSITIVE TERMINAL BLOCK CABLE	Prevost	2012-07-17	2012-07-17	2012-07-17	2012-09-30	62 256	92 172	154 428	4 198	6 87	10 285	77	51	67	0	0	0.2	Oct 31 2012: Vehicles repaired under former warranty bulletin WB10-04 are now included
7	12V-325	n/a	SR12-25	Front Suspension Torqueing	Prevost	2012-07-06	2012-07-06	2012-07-06	2012-09-30	8		8	8		8	100	n/a	100	0	0	0.2	This would be the first and last time that this recall is reported
8	12V-337	2012-221	SR12-26	Power Cable Protection	Prevost	2012-08-13	2012-08-13	2012-08-13	2012-09-30	211	80	291	54	9	63	26	11	22	0	0	0.1	
9	12V-435	n/a	SR12-29	AUTOMATIC FIRE DETECTION AND SUPPRESSION SYSTEM (AFSS) – PROTECTION OF LINEAR THERMAL DETECTOR (LTD)	Prevost	2012-09-27	2012-09-27	2012-09-27	2012-09-30	15	0	15	0	0	0	0	n/a	0	0	0	0.0	
10	11V-364	n/a	SR11-52	FUSEBOX CONNECTIONS-INSPECT AND TORQUE TIGHTEN	Volvo Bus	2011-07-20	2011-07-20	2011-07-20	2012-09-30	179	0	179	158	n/a	158	88	n/a	88	0	0	1.2	
11	12v-205	n/a	SR12-57	Emergency Windows - wheel chair lift vehicles	Volvo Bus	2012-09-26	2012-09-26	2012-09-26	2012-09-30	27	0	27	1	0	1	4	n/a		0	0	0.0	
12	12V-295	n/a	SR12-59	Bodywork SW Update	Volvo Bus	2012-07-13	2012-07-13	2012-07-13	2012-09-30	9		9	4		3	44	n/a	44.4	0	0	0.2	
13	12V-313	n/a	SR12-61	PASSENGER SEAT TRACK INSPECTION AND REPAIR	Volvo Bus	2012-09-24	2012-09-24	2012-09-24	2012-09-30	145	0	145	3	0	3	2	n/a	2.1	0	0	0.0	