

MERCEDES-BENZ USA, LLC.

December 31, 2012

MOTOR VEHICLE SAFETY DEFECT REPORT  
 QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS

MBUSA REFERENCE NUMBER ABBREVIATED DESCRIPTION	2011090001 ML BRAKE SWITCH	2011110002 ML, GL, R, E DIESEL FUEL FILTER	2012070006 E WAGON LEVEL SENSOR	2012090002 G INSTRUMENT PANEL	2012100001 SL A/C REFRIGERANT	2012110003 CLS HOOD LATCH
REPORT NO. (573.6)	5	5	2	1	1	1
CAMPAIGN NO. b(1)	11V-208	11V-496*	12V-264	12V-380	12V-478	12V-533
DATE STARTED b(2)	9/23/2011	11/23/2011	9/7/2012	10/19/2012	10/26/2012	11/21/2012
NOTIFICATION ENDED b(2)						
NUMBER OF VEHICLES						
INVOLVED IN CAMPAIGN: b(3)	135060	6785	3617	183	432	23
REPAIRED: b(4i)	39998	4861	2425	69	156	9
INSPECTED						
REPAIR NOT NEEDED: b(4ii)	0	0	0	0	0	0
CORRECTIVE MEASURES						
COMPLETED: b(5)	39998	4861	2425	69	156	9
UNREACHABLE b(6)	0	0	0	0	0	0
STOLEN	0	0	0	0	0	0
SCRAPPED	0	0	0	0	0	0
SOLD-OWNER UNKNOWN	0	0	0	0	0	0
OUT OF U.S.	0	0	0	0	0	0
MOVED-NO ADDRESS	0	0	0	0	0	0
UNCLAIMED LETTER	0	0	0	0	0	0
UNCOOPERATIVE	0	0	0	0	0	0
COMPLETION PERCENT	29.61%	71.64%	67.04%	37.70%	36.11%	39.13%

\* Per MBUSA's November 15, 2011 Part 573 Defect Information Report Update, Recall 10V-540 (2010110001) was closed on November 23, 2011 with the launch of Recall 11V-496. MBUSA will discontinue reporting on 10V-540 after fourth quarter 2011. Going forward, all of the vehicles will be covered and reported under MBUSA Recall Campaign Number 2011110002 (NHTSA recall number 11V-496).