



## ROADSTER Fuel Vapor Canister Vent Hose Campaigns - Re-Notification (U.S. Models Only) \_000109773\_MES61Y015S02\_en

[Printable  
Version](#)

Rate This Article



(Average Rating: No Rating)

Version 1

Language **English**

[Show Properties](#)

### Article Detail

Dear Can-Am® Spyder® roadster Dealer,

In cooperation with NHTSA, BRP is re-notifying some customers that their vehicle may still be affected by:

Safety Campaign Bulletin 2010-12:

Fuel Vapor Canister Vent Hose Inspection/Replacement

Campaign: 2008-013, 2009-0009 and 2010-0017

### What will BRP do?

BRP is sending Re-Notification Letters to the owners of a vehicle for which the above described campaigns are still pending.

### What should you do?

Follow instructions in Safety Bulletin 2010-12 that was originally sent to you in December 2012. These can also be found on BOSSWeb.

---

First Published By: Dany Davey on 02/27/2015

Last Modified By: Dany Davey on 02/27/2015