



# ROADSTER Safety Recall – Fire Hazard - Fuel Cap Replacement (U.S. Models Only) \_000109768\_MES61Y015S02\_en

Printable  
Version

Rate This Article



(Average Rating: No Rating)

Version 1

Language English

Show Properties

## Article Detail

### Problem

The fuel cap may not seal properly the fuel tank filler neck. Fuel vapors in the presence of an ignition source could result in a fire.

### What should you do?

When this vehicle is in your dealership, double-check that the fuel cap has been replaced with the correct version, as per [Safety Bulletin 2012-13](#).

If the fuel cap has NOT been replaced:

Replace the fuel cap.

Follow the bulletin instructions, refer to section: "Vehicle with a Fuel Cap Safety Recall package shipped to consumers".

Process a warranty claim using the following campaign numbers: 2008-14, 2009-0010, 2010-0018, 2011-0021 or 2012-0015.

If the fuel cap has been replaced: no further action is needed.

---

First Published By: Dany Davey on 02/26/2015

Last Modified By: Dany Davey on 02/27/2015