

IMPORTANT SAFETY RECALL

This notice applies to your vehicle



565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

«SERNR» «MODEL_YR» «CMP_NO»
«NAME2»«NAME3» «NAME1»
«STREET»
«CITY» «REGION» «ZIP»
«COUNTRY»

February 26, 2015

Re: Can-Am® Spyder® roadster - Fuel Vapor Canister Vent Hose Inspection/Replacement – Re-Notification

Dear Can-Am roadster Owner,

BRP is sending you this re-notification letter because our records show that you own a potentially affected vehicle that has not been inspected nor repaired yet.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

BRP has decided that a defect which relates to motor vehicle safety exists on certain Can-Am roadster models and launched a safety recall in December 2012.

What is the potential problem?

In some circumstances, fuel vapors may exit the fuel vapor canister vent hose in the enclosed engine compartment. Fuel vapors in the presence of an ignition source could result in a fire.

What should you do?

Call an authorized BRP Can-Am roadster dealer and make an appointment to have your fuel vapor canister vent hose inspected and if required replaced and re-routed. This part replacement should take less than one hour to complete. *The dealer will perform this work at no charge to you.* If you had this hose repaired before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

What to do if you feel this notice is an error?

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

If you believe that the dealer or BRP has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E. Washington, D.C. 20590, or call the toll free Auto Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>. If you are a vehicle lessor, federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Rotax
Can-Am

If you have questions, need assistance, or to find the nearest authorized BRP Can-Am roadster dealer:

- Visit www.can-am.brp.com
- Or call: 1-888-272-9222
9:00 AM to 9:00 PM Eastern time Monday to Friday

Your continued satisfaction with your roadster is important to us. Please understand that we have taken this action in the interest of your safety and your vehicle's proper operation. We apologize for any inconvenience this may cause you.

Thank you for your immediate attention to this matter.

Sincerely,
After-Sales Service Department