

U.S. Department of Transportation

# National Highway Traffic Safety Administration

June 10, 2013

Suite 400

Mr. Steve Kenner

Ford Motor Company
330 Town Center Drive

NVS-215KS
13V-232

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Reduced Steering Control

Dearborn, MI 48126-2738

Dear Mr. Kenner:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

### Makes/Models/Model Years:

FORD/FUSION/2013

Mfr's Report Date: May 28, 2013

NHTSA Campaign Number: 13V-232

**Components:** STEERING

**Potential Number of Units Affected: 20** 

### **Problem Description:**

Ford is recalling certain model year 2013 Fusion vehicles manufactured April 19, 2013, through April 23, 2013. The steering gears may be missing an internal retaining clip. If the clip is missing, components inside the steering gear may become dislodged inside the gear assembly.

#### **Consequence:**

This could result in impaired steering, including the loss of steering control, increasing the risk of a crash.

## Remedy:

Ford will notify owners, and dealers will replace the steering gear, free of charge. The recall is expected to begin in mid-June 2013. Ford's recall number is 13S06. Owners may contact the Ford customer relationship center at 1-866-436-7332.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Ford's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

