



TO: Winnebago Industries, Inc. Dealers

SUBJECT: Campaign #128 – Range Enclosure

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2012, 2013, and 2014 Model Year Winnebago® (Models: Minnie Winnie®, Chalet®, Aspect®, Sightseer®, Adventurer®, and Journey®). Certain 2012, 2013, and 2014 Model Year Itasca® (Models: Spirit®, Cambria®, Sunova®, Suncruiser®, and Meridian®).

These motorhomes were manufactured January 10, 2012 through April 5, 2013. These vehicles may have a missing range enclosure that isolates the range from air movement that could put out the flame. Either positive or negative airflow can disrupt the flame and may extinguish the flame. If the range flame goes out and the propane gas continues to flow, it has the potential to ignite resulting in personal injury and/or vehicle and property damage.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Winnebago Industries, Inc. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward. Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

DJ205 US/3

P.O. Box 152 • 605 West Crystal Lake Road • Forest City, Iowa 50436 • PH: 641/585-3535 • FAX: 641/585-6966
<http://www.winnebagoind.com>

INSTRUCTION TO PERFORM CAMPAIGN #128

Affected Models:

- Certain 2012, 2013, and 2014 Model Year Winnebago (Models: Minnie Winnie, Chalet, Aspect, Sightseer, Adventurer, and Journey).
- Certain 2012, 2013, and 2014 Model Year Itasca (Models: Spirit, Cambria, Sunova, Suncruiser, and Meridian).

Repair Procedure:

Refer to instruction sheet for installation of range enclosure.

Parts Information:

To minimize any inconvenience to your customers, we strongly encourage you to promptly order part kits for the vehicles on the attached list. This will ensure you have adequate inventory for your customers. Order the following Part Kit from Winnebago Industries® using the WinPortal system. You will be placing the order as a recall order. You will need the recall dealer number and the Winnebago Industries serial number of the affected vehicle to place the order.

- Part Number RC7698-13-728 is for Atwood® range top installation.
- Part Number RC7699-13-728 is for Atwood range with oven installation.
- Part Number RC7600-13-728 is for Suburban® range top installation.

Dealer Number: 7698		
Qty.	Part Description	Part Number
1	Instruction Sheet	RC7698-13-728
1	Range Enclosure	

Dealer Number: 7600		
Qty.	Part Description	Part Number
1	Instruction Sheet	RC7600-13-728
1	Range Enclosure	

Dealer Number: 7699		
Qty.	Part Description	Part Number
1	Instruction Sheet	RC7699-13-728
1	Range Enclosure	

REIMBURSEMENT

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

	OPERATION NUMBER	OPERATION NUMBER	OPERATION NUMBER
	Dealer No.: 7698	Dealer No.: 7699	Dealer No.: 7600
INSTALLATION OF			
RANGE ENCLOSURE	24280101	24280201	24280301
TIME ALLOWANCE	0.7 hr.	0.7 hr.	0.7 hr.

Thank you for your cooperation.

Winnebago Industries, Inc.
Forest City, Iowa 50436

Enclosures
DJ205 US/4