

GM CUSTOMER CARE AND AFTERSALES
DCS3685
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 17, 2015

Subject: 12213A – Safety Recall
Brake Vacuum Micro Switch
Revised Service Procedure, Parts and Warranty Information

Models: 2011-2012 Chevrolet Cruze
Equipped with 1.4L DOHC Turbo Engine (LUJ) and 6T40
FWD Automatic Transmission (MH8)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The parts information, service procedure and warranty transaction Information sections have been revised. The vehicle repair has been revised to replace the power brake booster vacuum pipe, which includes the vacuum micro switch. Vehicles previously repaired under this recall do not need any additional repairs. Please discard all copies of bulletin 12213.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES