

Date of Letter

IMPORTANT SAFETY RECALL

This notice applies to your vehicle; VIN

SUBJECT: SAFETY RECALL # 113-A Models 579 and 567 Air Suspension Dump Control
NHTSA Recall # 13V-027
EXPIRATION DATE: NONE

Customer Name
Customer Address
City, State Zip

**IMPORTANT
THIS IS A REMINDER**

Dear Peterbilt Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain Peterbilt Model 579 and 567 vehicles with the option for Air Suspension Dump and/or Trailer Air Suspension Dump, manufactured between November 29, 2012 and December 6, 2012. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

Models 579 and 567 with the Air Suspension Dump option will re-inflate a deflated rear air suspension without warning when the ignition key is turned to the "OFF" position. This unexpected re-inflation of the suspension could result in physical injury to a person near the rear suspension. Subsequently turning the key to the "on" position will deflate the rear suspension.

<i>The problem is...</i>	Improper inflating and deflating of the rear air suspension
<i>What your dealer will do...</i>	Reprogram software on your vehicle to the updated version software
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Peterbilt Motors Company has initiated a recall to reprogram your trucks software. Please contact your Peterbilt dealer immediately to schedule an appointment for this repair. To find the nearest Peterbilt dealer, please visit Dealer Locator at www.Peterbilt.com. This repair should take less than one half hour, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.


If you require further information, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook Street, Denton, Texas 76205; Customer Service Department, phone 940-591-4220.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise.

We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Doug Gunter
Director of Customer Service
Peterbilt Motors Company