

Cheetah Chassis Corporation

225 Lincoln Highway
Fairless Hills, PA 19030



Phone: (215) 949-4741 3600

FAX: (215) 949-4779

~~www.cheetah.com~~

www.cheetahchassis.com

IMPORTANT SAFETY RECALL

This notice applies to your vehicles identified on the enclosed spreadsheet

November 22, 2013

CERTIFIED MAIL – R.R.R.

XTRA, LLC
Attn: Steve Zaborowski
7911 Forsyth Blvd.
Suite 600
St. Louis, MO 63105

Dear Mr. Zaborowski:

This notice is sent in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cheetah Chassis Corporation ("Cheetah Chassis") has determined that a defect which relates to motor vehicle safety exists in your trailers identified on the enclosed spreadsheet.

The defect is contained in the curbside and roadside locating pins that are designed to limit the rearward movement of the suspension during the repositioning of the axle group during loading operations. The defect is identified as a fracture in the weld joining the pin's shaft and collar that can initiate under certain loading conditions. Repeated impacts to the locating pins during loading operations may cause the fractures to increase in size, leading to separation of the pin's shaft and collar. Separation of the locating pin's shaft and collar may allow these parts to become separated from the vehicle and fall onto the roadway while the vehicle is in operation, which could result in serious injury to other motorists or property damage to other vehicles. In addition, if both locating pins are lost from the vehicle, the vehicle's suspension section may become separated during the repositioning procedure, posing a risk of damage to the vehicle or injury to persons who may be in close proximity to the vehicle at the time of a separation.

In order to remedy the defect, it will be necessary to replace the curbside and roadside locating pins on your vehicles in accordance with the instructions attached to this letter. The locating pin assemblies must be replaced even if they do not currently exhibit any weld fractures. We will supply the new replacement pin assemblies without cost and will ship them to multiple locations at your request. The assemblies are expected to be available for delivery beginning on December 9, 2013. We will also reimburse you for the reasonable direct labor costs involved in effecting the repair or will have the

XTRA, LLC
November 22, 2013
Page 2

repair facilities bill us directly. The work to replace the locating pins will take approximately one hour to perform.

We will make ourselves available to answer any questions that arise during the course of this modification program, and, if requested, assist you in locating qualified repair facilities. We will also provide training or any other support you need. If you need any assistance, please contact me, Jerry Clontz, at jclontz@diamatrix.net or 1-704-436-2590.

Invoices for completed work should be submitted with authorization number 2013007 and a list of vehicle identification numbers for the serviced equipment to:

Cheetah Chassis Corporation
3rd & Oak Streets
P.O. Box 388
Berwick, PA 18603

If you have had your vehicle repaired prior to receipt of this notice, you may be entitled to reimbursement if you incurred any out-of-pocket cost due to this matter. For further information, please contact us at 1-704-436-2590.

Federal law requires any lessor who receives a notification of a determination of a safety-related defect or noncompliance pertaining to any leased motor vehicle to send the notice to the lessee within 10 days.

We regret any inconvenience this action may cause you. However, we are concerned about your safety, and we have notified the National Highway Traffic Safety Administration of this program. If you are unable to have these defects remedied without charge, you may submit a complaint to:

Administrator, U.S. Department of Transportation
National Highway Traffic Safety Administration
Office of Defects Investigation
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Alternatively, you may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

Thank you for your attention to this important matter.




Very truly yours,

Jerry Clontz


Installation Instructions for the 20/40 Maximizer Locating Pin Replacement:

Step 1: Please read all instructions completely and make sure you understand before starting this repair.

Step 2: Find locating pin on the front portion of bogie rail assembly on trailer. Approximately shown with arrows in the figures below.




Step 3: Remove the existing locating pin from the bogie assembly. Remove $\frac{1}{2}$ " nut and bolt with $\frac{3}{4}$ " wrench and remove collar. The pin should slide out easily. Clean debris from hole after pin is removed if necessary.



Step 4: Insert the new locating pin item (401613) thru hole on frame rail assembly as shown below with larger outside diameter facing outboard.

(Note: The new locating pin item (401613) is a single machined part.)

Below Figure: Cutout, exploded view, of locating pin assembly (95680) inside bogie of 20/40 Maximizer.



Step 5: Install collar item (95677) on pin (401613). Turn collar until hole is aligned with the hole on pin. Install bolt (96041) and nut (00287) thru hole in collar (95677) and pin (401613).

Step 6: Tighten bolt (96041) until nut (00287) contacts outside diameter of collar (95677). 5 threads should be showing thru nut.

Step 7: Repeat process steps 2 to 6 on opposite side of trailer.

Item Description Table	
Part Number	Description
95680	STOP, INSTALL, 3.0"DIA, PIN, 2040 STD (Assembly)
401613	SHAFT, 1.875"OD X 3"OD X8.06", STOP, 2040STD
96041	BOLT, HHC, .500-13X 4"
95677	COLLAR, 3"OD X 0.5"W X 1.0 LG, W/HOLE
00287	NUT, LOCK, ESLOK,ZP,.500-13

20-40 FT MAXIMIZER CHASSIS RECALL

1 OF 5

VIN #	MODEL YEAR	TYPE	MODEL #	ISSUE DATE	CUSTOMER
SEF3GC412AB774209	2010	CHASSIS	8410GNFF2	09/14/09	XTRA LLC
SEF3GC410AB774211	2010	CHASSIS	8410GNFF2	09/14/09	XTRA LLC
SEF3GC412AB774212	2010	CHASSIS	8410GNFF2	09/14/09	XTRA LLC
SEF3GC419AB774210	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC414AB774213	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC416AB774214	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC418AB774215	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC41XAB774216	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC411AB774217	2010	CHASSIS	8410GNFF2	09/16/09	XTRA LLC
SEF3GC413AB774218	2010	CHASSIS	8410GNFF2	09/17/09	XTRA LLC
SEF3GC415AB774219	2010	CHASSIS	8410GNFF2	09/17/09	XTRA LLC
SEF3GC411AB774220	2010	CHASSIS	8410GNFF2	09/17/09	XTRA LLC
SEF3GC413AB774221	2010	CHASSIS	8410GNFF2	09/17/09	XTRA LLC
SEF3GC415AB774222	2010	CHASSIS	8410GNFF2	09/22/09	XTRA LLC
SEF3GC410AB774208	2010	CHASSIS	8410GNFF2	09/23/09	XTRA LLC
SEF3GC417AB774223	2010	CHASSIS	8410GNFF2	09/23/09	XTRA LLC
SEF3GC419AB774224	2010	CHASSIS	8410GNFF2	09/23/09	XTRA LLC
SEF3GC412AB774226	2010	CHASSIS	8410GNFF2	09/30/09	XTRA LLC
SEF3GC414AB774227	2010	CHASSIS	8410GNFF2	09/30/09	XTRA LLC
SEF3GC416AB774228	2010	CHASSIS	8410GNFF2	09/30/09	XTRA LLC
SEF3GC418AB774229	2010	CHASSIS	8410GNFF2	09/30/09	XTRA LLC
SEF3GC414AB774230	2010	CHASSIS	8410GNFF2	10/01/09	XTRA LLC
SEF3GC416AB774231	2010	CHASSIS	8410GNFF2	10/01/09	XTRA LLC
SEF3GC418AB774232	2010	CHASSIS	8410GNFF2	10/01/09	XTRA LLC
SEF3GC41XAB774233	2010	CHASSIS	8410GNFF2	10/01/09	XTRA LLC
SEF3GC411AB774234	2010	CHASSIS	8410GNFF2	10/06/09	XTRA LLC
SEF3GC413AB774235	2010	CHASSIS	8410GNFF2	10/13/09	XTRA LLC
SEF3GC415AB774236	2010	CHASSIS	8410GNFF2	10/14/09	XTRA LLC
SEF3GC417AB774237	2010	CHASSIS	8410GNFF2	10/14/09	XTRA LLC
SEF3GC419AB774238	2010	CHASSIS	8410GNFF2	10/15/09	XTRA LLC
SEF3GC410AB774239	2010	CHASSIS	8410GNFF2	10/15/09	XTRA LLC
SEF3GC417AB774240	2010	CHASSIS	8410GNFF2	10/15/09	XTRA LLC
SEF3GC419AB774241	2010	CHASSIS	8410GNFF2	10/19/09	XTRA LLC

20-40 FT MAXIMIZER CHASSIS RECALL

2 OF 5

5EF3GC410AB774242	2010	CHASSIS	8410GNFF2	10/19/09	XTRA LLC
5EF3GC412AB774243	2010	CHASSIS	8410GNFF2	10/19/09	XTRA LLC
5EF3GC414AB774244	2010	CHASSIS	8410GNFF2	10/19/09	XTRA LLC
5EF3GC416AB774245	2010	CHASSIS	8410GNFF2	10/19/09	XTRA LLC
5EF3GC418AB774246	2010	CHASSIS	8410GNFF2	10/20/09	XTRA LLC
5EF3GC41XAB774247	2010	CHASSIS	8410GNFF2	10/20/09	XTRA LLC
5EF3GC411AB774248	2010	CHASSIS	8410GNFF2	10/20/09	XTRA LLC
5EF3GC413AB774249	2010	CHASSIS	8410GNFF2	10/21/09	XTRA LLC
5EF3GC41XAB774250	2010	CHASSIS	8410GNFF2	10/21/09	XTRA LLC
5EF3GC411AB774251	2010	CHASSIS	8410GNFF2	10/22/09	XTRA LLC
5EF3GC413AB774252	2010	CHASSIS	8410GNFF2	10/27/09	XTRA LLC
5EF3GC415AB774253	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC417AB774254	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC419AB774255	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC410AB774256	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC412AB774257	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC414AB774258	2010	CHASSIS	8410GNFF2	10/28/09	XTRA LLC
5EF3GC416AB774259	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC412AB774260	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC414AB774261	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC416AB774262	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC418AB774263	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC41XAB774264	2010	CHASSIS	8410GNFF2	10/29/09	XTRA LLC
5EF3GC411AB774265	2010	CHASSIS	8410GNFF2	11/02/09	XTRA LLC
5EF3GC413AB774266	2010	CHASSIS	8410GNFF2	11/03/09	XTRA LLC
5EF3GC415AB774267	2010	CHASSIS	8410GNFF2	11/03/09	XTRA LLC
5EF3GC417AB774268	2010	CHASSIS	8410GNFF2	11/04/09	XTRA LLC
5EF3GC419AB774269	2010	CHASSIS	8410GNFF2	11/04/09	XTRA LLC
5EF3GC415AB774270	2010	CHASSIS	8410GNFF2	11/04/09	XTRA LLC
5EF3GC417AB774271	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC
5EF3GC419AB774272	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC
5EF3GC410AB774273	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC
5EF3GC412AB774274	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC
5EF3GC414AB774275	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC
5EF3GC416AB774276	2010	CHASSIS	8410GNFF2	11/05/09	XTRA LLC

20-40 FT MAXIMIZER CHASSIS RECALL

5EF3GC418AB774277	2010	CHASSIS	8410GNFF2	11/10/09	XTRA LLC
5EF3GC41XAB774278	2010	CHASSIS	8410GNFF2	11/10/09	XTRA LLC
5EF3GC411AB774279	2010	CHASSIS	8410GNFF2	11/10/09	XTRA LLC
5EF3GC418AB774280	2010	CHASSIS	8410GNFF2	11/12/09	XTRA LLC
5EF3GC41XAB774281	2010	CHASSIS	8410GNFF2	11/12/09	XTRA LLC
5EF3GC411AB774282	2010	CHASSIS	8410GNFF2	11/25/09	XTRA LLC
5EF3GC410DB779543	2013	CHASSIS	8410GNFF2	06/28/12	XTRA LLC
5EF3GC412DB779544	2013	CHASSIS	8410GNFF2	06/28/12	XTRA LLC
5EF3GC414DB779545	2013	CHASSIS	8410GNFF2	06/28/12	XTRA LLC
5EF3GC416DB779546	2013	CHASSIS	8410GNFF2	07/03/12	XTRA LLC
5EF3GC418DB779547	2013	CHASSIS	8410GNFF2	07/09/12	XTRA LLC
5EF3GC41XDB779548	2013	CHASSIS	8410GNFF2	07/09/12	XTRA LLC
5EF3GC411DB779549	2013	CHASSIS	8410GNFF2	07/10/12	XTRA LLC
5EF3GC418DB779550	2013	CHASSIS	8410GNFF2	07/10/12	XTRA LLC
5EF3GC418EB780327	2014	CHASSIS	8410GNFF2	02/13/13	XTRA LLC
5EF3GC41XEB780328	2014	CHASSIS	8410GNFF2	02/13/13	XTRA LLC
5EF3GC411EB780329	2014	CHASSIS	8410GNFF2	02/13/13	XTRA LLC
5EF3GC416EB780326	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC418EB780330	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC41XEB780331	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC411EB780332	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC413EB780333	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC415EB780334	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC417EB780335	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC419EB780336	2014	CHASSIS	8410GNFF2	02/14/13	XTRA LLC
5EF3GC410EB780337	2014	CHASSIS	8410GNFF2	02/18/13	XTRA LLC
5EF3GC412EB780338	2014	CHASSIS	8410GNFF2	02/18/13	XTRA LLC
5EF3GC414EB780339	2014	CHASSIS	8410GNFF2	02/18/13	XTRA LLC
5EF3GC410EB780340	2014	CHASSIS	8410GNFF2	02/18/13	XTRA LLC
5EF3GC412EB780341	2014	CHASSIS	8410GNFF2	02/19/13	XTRA LLC
5EF3GC414EB780342	2014	CHASSIS	8410GNFF2	02/19/13	XTRA LLC
5EF3GC416EB780343	2014	CHASSIS	8410GNFF2	02/19/13	XTRA LLC
5EF3GC41XEB780345	2014	CHASSIS	8410GNFF2	02/20/13	XTRA LLC
5EF3GC411EB780346	2014	CHASSIS	8410GNFF2	02/20/13	XTRA LLC
5EF3GC413EB780347	2014	CHASSIS	8410GNFF2	02/20/13	XTRA LLC

20-40 FT MAXIMIZER CHASSIS RECALL

5EF3GC418EB780344	2014	CHASSIS	8410GNFF2	02/21/13	XTRA LLC
5EF3GC415EB780348	2014	CHASSIS	8410GNFF2	02/21/13	XTRA LLC
5EF3GC417EB780349	2014	CHASSIS	8410GNFF2	02/21/13	XTRA LLC
5EF3GC413EB780350	2014	CHASSIS	8410GNFF2	02/21/13	XTRA LLC
5EF3GC415EB780351	2014	CHASSIS	8410GNFF2	02/21/13	XTRA LLC
5EF3GC417EB780352	2014	CHASSIS	8410GNFF2	02/26/13	XTRA LLC
5EF3GC419EB780353	2014	CHASSIS	8410GNFF2	02/26/13	XTRA LLC
5EF3GC410EB780354	2014	CHASSIS	8410GNFF2	02/26/13	XTRA LLC
5EF3GC412EB780355	2014	CHASSIS	8410GNFF2	02/26/13	XTRA LLC
5EF3GC414EB780356	2014	CHASSIS	8410GNFF2	02/26/13	XTRA LLC
5EF3GC416EB780357	2014	CHASSIS	8410GNFF2	02/27/13	XTRA LLC
5EF3GC418EB780358	2014	CHASSIS	8410GNFF2	02/27/13	XTRA LLC
5EF3GC41XEB780359	2014	CHASSIS	8410GNFF2	02/27/13	XTRA LLC
5EF3GC416EB780360	2014	CHASSIS	8410GNFF2	02/28/13	XTRA LLC
5EF3GC418EB780361	2014	CHASSIS	8410GNFF2	02/28/13	XTRA LLC
5EF3GC41XEB780362	2014	CHASSIS	8410GNFF2	02/28/13	XTRA LLC
5EF3GC411EB780363	2014	CHASSIS	8410GNFF2	03/04/13	XTRA LLC
5EF3GC413EB780364	2014	CHASSIS	8410GNFF2	03/04/13	XTRA LLC
5EF3GC415EB780365	2014	CHASSIS	8410GNFF2	03/04/13	XTRA LLC
5EF3GC417EB780366	2014	CHASSIS	8410GNFF2	03/05/13	XTRA LLC
5EF3GC419EB780367	2014	CHASSIS	8410GNFF2	03/05/13	XTRA LLC
5EF3GC410EB780368	2014	CHASSIS	8410GNFF2	03/05/13	XTRA LLC
5EF3GC412EB780369	2014	CHASSIS	8410GNFF2	03/05/13	XTRA LLC
5EF3GC419EB780370	2014	CHASSIS	8410GNFF2	03/06/13	XTRA LLC
5EF3GC410EB780371	2014	CHASSIS	8410GNFF2	03/06/13	XTRA LLC
5EF3GC412EB780372	2014	CHASSIS	8410GNFF2	03/06/13	XTRA LLC
5EF3GC414EB780373	2014	CHASSIS	8410GNFF2	03/07/13	XTRA LLC
5EF3GC416EB780374	2014	CHASSIS	8410GNFF2	03/07/13	XTRA LLC
5EF3GC418EB780375	2014	CHASSIS	8410GNFF2	03/07/13	XTRA LLC
5EF3GC41XEB780376	2014	CHASSIS	8410GNFF2	03/07/13	XTRA LLC
5EF3GC411EB780377	2014	CHASSIS	8410GNFF2	03/11/13	XTRA LLC
5EF3GC413EB780378	2014	CHASSIS	8410GNFF2	03/11/13	XTRA LLC
5EF3GC415EB780379	2014	CHASSIS	8410GNFF2	03/11/13	XTRA LLC
5EF3GC411EB780380	2014	CHASSIS	8410GNFF2	03/12/13	XTRA LLC
5EF3GC413EB780381	2014	CHASSIS	8410GNFF2	03/12/13	XTRA LLC

20-40 FT MAXIMIZER CHASSIS RECALL

5 OF 5

5EF3GC415EB780382	2014	CHASSIS	8410GNFF2	03/12/13	XTRA LLC
5EF3GC417EB780383	2014	CHASSIS	8410GNFF2	03/12/13	XTRA LLC
5EF3GC419EB780384	2014	CHASSIS	8410GNFF2	03/13/13	XTRA LLC
5EF3GC410EB780385	2014	CHASSIS	8410GNFF2	03/13/13	XTRA LLC
5EF3GC412EB780386	2014	CHASSIS	8410GNFF2	03/13/13	XTRA LLC
5EF3GC414EB780387	2014	CHASSIS	8410GNFF2	03/13/13	XTRA LLC
5EF3GC416EB780388	2014	CHASSIS	8410GNFF2	03/13/13	XTRA LLC
5EF3GC418EB780389	2014	CHASSIS	8410GNFF2	03/18/13	XTRA LLC
5EF3GC414EB780390	2014	CHASSIS	8410GNFF2	03/18/13	XTRA LLC
5EF3GC416EB780391	2014	CHASSIS	8410GNFF2	03/18/13	XTRA LLC
5EF3GC418EB780392	2014	CHASSIS	8410GNFF2	03/18/13	XTRA LLC
5EF3GC41XEB780393	2014	CHASSIS	8410GNFF2	03/19/13	XTRA LLC
5EF3GC411EB780394	2014	CHASSIS	8410GNFF2	03/19/13	XTRA LLC
5EF3GC413EB780395	2014	CHASSIS	8410GNFF2	03/20/13	XTRA LLC
5EF3GC415EB780396	2014	CHASSIS	8410GNFF2	03/20/13	XTRA LLC
5EF3GC417EB780397	2014	CHASSIS	8410GNFF2	03/20/13	XTRA LLC
5EF3GC419EB780398	2014	CHASSIS	8410GNFF2	03/20/13	XTRA LLC
5EF3GC410EB780399	2014	CHASSIS	8410GNFF2	03/20/13	XTRA LLC
5EF3GC413EB780400	2014	CHASSIS	8410GNFF2	03/21/13	XTRA LLC
5EF3GC415EB780401	2014	CHASSIS	8410GNFF2	03/21/13	XTRA LLC
5EF3GC417EB780402	2014	CHASSIS	8410GNFF2	03/25/13	XTRA LLC
5EF3GC419EB780403	2014	CHASSIS	8410GNFF2	03/25/13	XTRA LLC
5EF3GC410EB780404	2014	CHASSIS	8410GNFF2	03/25/13	XTRA LLC
5EF3GC412EB780405	2014	CHASSIS	8410GNFF2	03/25/13	XTRA LLC
5EF3GC414EB780406	2014	CHASSIS	8410GNFF2	03/25/13	XTRA LLC



Cheetah Chassis Corporation
225 Lincoln Highway
Fairless Hills, PA 19030

Run... with the Best

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:
XTRA, LLC
Attn: Stephen Zaborowski
7911 Forsyth Blvd., Ste. 600
St. Louis, MO 63105

COMPLETE THIS SECTION ON DELIVERY

A. Signature ☒ Agent
☐ Addressee

B. Received by (Printed Name) ☐ Date of Delivery

D. Is delivery address different from item 1? ☐ Yes
If YES, enter delivery address below: ☐ No

3. Service Type

☒ Certified Mail ☐ Express Mail
☐ Registered ☐ Return Receipt for Merchandise
☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Transfer from service label) 7012 1640 0000 7602 0769
PS Form 3811, February 2004 Domestic Return Receipt

PLACE STICKER AT TOP OF ENVELOPE TO THE RIGHT OF THE RETURN ADDRESS. FOLD AT DOTTED LINE.
CERTIFIED MAIL™



7012 1640 0000 7602 0769
7012 1640 0000 7602 0769

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)
For delivery information visit our website at www.usps.com.

OFFICIAL USE

Postage	\$
Certified Fee	
Return Receipt Fee (Endorserment Required)	
Restricted Delivery Fee (Endorserment Required)	
Total Postage & Fees	\$

Postmark
Here

Sent to

Street, Apt. No.,

or PO Box No.

City, State, ZIP+4

XTRA

PS Form 3800 August 2005

See Reverse for Instructions

IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance
With Federal Law
NHTSA
U.S. Department of Transportation

XTRA, LLC
Attn: Stephen Zaborowski, Senior V. P.
7911 Forsyth Blvd., Suite 600
St. Louis, MO 63105