


★ **IMPORTANT SAFETY RECALL REMINDER:**

VIN:

**HAVE YOU HAD YOUR SUZUKI GSX-R'S FRONT BRAKE
MASTER CYLINDER INSPECTED AND REPLACED?**



★ **Be sure to take care of this immediately!**

**Contact Suzuki Motor of America Customer Service
at (714) 572-1490, 8:30 AM to 4:45 PM PST
or visit <http://www.suzukicycles.com/Recall>**





SUZUKI

Way of Life!

IMPORTANT SAFETY RECALL REMINDER



This is a Safety Recall follow-up reminder.

In November of 2013, Suzuki Motor Corporation determined that a defect related to motor vehicle safety exists in some 2004 - 2013 GSX-R600, GSX-R750 and GSX-R1000 motorcycles.

According to our records, your Suzuki motorcycle is affected by this Safety Recall, but you have not yet had the necessary repair performed.

The repair requires the replacement of the front brake master cylinder and brake fluid. The repair will be performed at no charge, and requires approximately 2 hours. Replacement parts are available; there is no reason to delay this repair.

Please contact your Suzuki dealer as soon as possible to schedule the repair. You may locate your nearest Suzuki dealer by checking the following website: <http://www.suzukicycles.com/dealers.aspx>

It is possible that your motorcycle might also be affected by another Safety Recall campaign. You can find out by providing the motorcycle's VIN to your dealer or by entering it at <http://www.suzukicycles.com/Recalls.aspx> or <https://vinrcl.safercar.gov/vin/>.

It is also possible that this repair has already been performed; please confirm this with your Suzuki dealer before dismissing this notice.

If you have questions regarding this campaign, please contact Suzuki at (714) 572-1490, 8:30 AM – 4:45 PM PST.