

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Thomas Built Bus Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090 FAX 503-745-9009

If you have questions about this Letter, please submit your inquiry on the Web at:

[AccessFreightliner.com / Support / My Tickets and Submit an Inquiry](http://AccessFreightliner.com/Support/MyTicketsandSubmitanInquiry)

REF #: ICI14-002

Effective: 02/03/14

Release: 01/31/14

SUBJECT: Eaton Recall – Hybrid Transmission Software

This letter is to inform you that DTNA is sending notices in support of a recall being conducted by Eaton Corporation, *Eaton Hybrid Transmission Control Module Software*. They will be mailed the week of 02/03/14. Copies of the notices to U.S. and Canadian customers and a list of affected VINs are attached for your reference.

Eaton is conducting the recall, and all claims will be submitted to Eaton.

All questions should be directed to Eaton. Contact information is:

Eaton Corporation
Attention: Roadranger Call Center
13100 E Michigan Avenue
Galesburg, MI 49053
(800) 826-4357
GaryA.Pfister@eaton.com

If you have questions or need further information, please contact Eaton as noted above.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

January 2014

NHTSA #13V-634 (Non-School Buses)

#13V-633 (School Buses)

#13E-068

IMPORTANT SAFETY RECALL

Subject: Eaton Hybrid Transmission Control Module Software

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler Trucks North America LLC (DTNA) is providing this Recall Notice with respect to certain vehicles with equipment manufactured by Eaton Corporation plc ("Eaton"). The vehicles affected are specific Freightliner Business Class M2, Freightliner Custom Chassis MT45 and MT55 walk-in van chassis, and Thomas Built Buses Saf-T-Liner C2 buses manufactured September 30, 2013, through December 10, 2013, or that received certain updates to the Eaton hybrid transmission software during a service visit February 2, 2013, through December 6, 2013.

DTNA and Eaton have decided that a defect which relates to motor vehicle safety exists in the vehicles mentioned above.

During downshifts where the current gear remains engaged or reengages due to a mechanical or system fault, the software logic in the Hybrid Control Module of the transmission can potentially result in unintended acceleration during a downshift. This defect can cause a crash without prior warning.

Eaton will remedy the defect by removing Hybrid Control Module software versions 5500682 and 5500683 and replacing it with software version 5500689, which eliminates the issue.

Please contact an authorized Eaton location to arrange to have this Recall completed. See the enclosed Eaton Recall Notice for details.

For questions regarding this Recall, please contact Eaton at (800) 826-4357.

If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you feel you are not able to have this defect remedied in a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure

P.O. Box 4013 | Kalamazoo, Michigan 49003

IMPORTANT SAFETY RECALL – 13E-068

January 10, 2014

Re: Safety Recall Eaton Hybrid Transmission

Model Name: Eaton Hybrid Transmission

Recall Applies Only to Hybrid Control Module Software versions 5500682 or 5500683

Models Involved:

EH-6E606B-CD; EH-6E606B-U; EH-6E606B-UP; EH-6E706B-UPG; EH-6E606B-T;
EH-6E606B-CDG; EH-6E606B-P; EH-6E606B-CDR; EH-6E606B-PBD; EH-6E706B-PSB;
EH-6E606B-PBD

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Eaton Corporation plc ("Eaton") has decided that a defect which relates to motor vehicle safety exists in certain of the above-referenced Hybrid Transmission models produced from August 2010 through December 2013 with the above noted software revisions.

REASON FOR THE RECALL

This defect arises in the above-referenced transmissions containing Hybrid Control Module software versions 5500682 or 5500683. Software version 5500682 was released on February 2, 2013 to Eaton's field service organization for download to transmissions as a field software update. Software version 5500683 was released to the field on June 20, 2013. Eaton's field service organization tracks electronically all downloads of the software version by vehicle identification number (VIN). The software version is not externally visible on the transmission. The list of impacted VIN numbers is attached.

Vehicle symptoms may arise in downshifts of the Eaton Hybrid Transmission loaded with Hybrid Control Module software versions 5500682 or 5500683. During downshifts where the current gear remains engaged or reengages due to a mechanical or system fault, the software logic in the Hybrid Control Module of the transmission can potentially result in unintended acceleration during a downshift. This defect can cause a crash without prior warning

WHAT WE WILL DO

- Eaton will remedy the defect by removing Hybrid Control Module software versions 5500682 and 5500683 from all Hybrid Transmissions on which it is installed and replacing it with software version 5500689, which eliminates the issue.
- Remedies can commence immediately as software version 5500689 is available as of December 11, 2013. Eaton is working cooperatively with vehicle manufacturers to identify the affected units.
- Eaton will provide the software update for the recalled Hybrid Transmissions at no charge. You must supply a detailed breakdown of actual expenses on a per vehicle basis including the number of hours and the actions taken. Eaton will use its Roadranger Call Center for working with customers and the associated reimbursement. The repair requires downloading new software into the transmission, the estimated repair time is one hour.

WHAT YOU SHOULD DO

Please contact your Eaton Representative or the Roadranger Call Center to have your software version updated for the affected VINs. If there are questions about the VINs, contact the Roadranger Call Center.

Direct any questions that you may have to your Eaton Customer Support Representative or the Roadranger Call Center (follow prompts to Hybrid Electric support):

Attn: Roadranger Call Center
Eaton Corporation
13100 E. Michigan Avenue
Galesburg, MI 49053
Tel: **800-826-4357**
Hybrid.RTW@eaton.com

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your distributor fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Eaton Corporation

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

**January 2014
Transport Canada #13-448**

IMPORTANT SAFETY RECALL

Subject: Eaton Hybrid Transmission Control Module Software

This notice is sent to you in accordance with the Canadian Motor Vehicle Safety Act..

Daimler Trucks North America LLC (DTNA) is providing this Recall Notice with respect to certain vehicles with equipment manufactured by Eaton Corporation plc ("Eaton"). The vehicles affected are specific Freightliner Business Class M2, Freightliner Custom Chassis MT45 and MT55 walk-in van chassis, and Thomas Built Buses Saf-T-Liner C2 buses manufactured September 30, 2013, through December 10, 2013, or that received certain updates to the Eaton hybrid transmission software during a service visit February 2, 2013, through December 6, 2013.

DTNA and Eaton have decided that a defect which relates to motor vehicle safety exists in the vehicles mentioned above.

During downshifts where the current gear remains engaged or reengages due to a mechanical or system fault, the software logic in the Hybrid Control Module of the transmission can potentially result in unintended acceleration during a downshift. This defect can cause a crash without prior warning.

Eaton will remedy the defect by removing Hybrid Control Module software versions 5500682 and 5500683 and replacing it with software version 5500689, which eliminates the issue.

Please contact an authorized Eaton location to arrange to have this Recall completed. See the enclosed Eaton Recall Notice for details.

For questions regarding this Recall, please contact Eaton at (800) 826-4357.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure



Eaton Corporation
Vehicle Group
13100 East Michigan Avenue
Galesburg, MI 49053
269-342-3000

IMPORTANT SAFETY RECALL

January 10, 2014

Re: Safety Recall Eaton Hybrid Transmission

Model Name: Eaton Hybrid Transmission

Recall Applies Only to Hybrid Control Module Software versions 5500682 or 5500683

Models Involved:

EH-6E606B-CD; EH-6E606B-U; EH-6E606B-UP; EH-6E706B-UPG; EH-6E606B-T;
EH-6E606B-CDG; EH-6E606B-P; EH-6E606B-CDR; EH-6E606B-PBD; EH-6E706B-PSB;
EH-6E606B-PBD

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Eaton Corporation plc ("Eaton") has determined that a defect which relates to motor vehicle safety exists in certain of the above-referenced Hybrid Transmission models produced from August 2010 through December 2013 with the above noted software revisions.

REASON FOR THE RECALL

This defect arises in the above-referenced transmissions containing Hybrid Control Module software versions 5500682 or 5500683. Software version 5500682 was released on February 2, 2013 to Eaton's field service organization for download to transmissions as a field software update. Software version 5500683 was released to the field on June 20, 2013. Eaton's field service organization Eaton tracks electronically all downloads of the software version by vehicle identification number (VIN). The software version is not externally visible on the transmission. The list of impacted VIN numbers is attached.

Vehicle symptoms may arise in downshifts of the Eaton Hybrid Transmission loaded with Hybrid Control Module software versions 5500682 or 5500683. During downshifts where the current gear remains engaged or reengages due to a mechanical or system fault, the software logic in the Hybrid Control Module of the transmission can potentially result in unintended acceleration during a downshift. This defect can cause a crash without prior warning.

WHAT WE WILL DO

- Eaton will remedy the defect by removing Hybrid Control Module software versions 5500682 and 5500683 from all Hybrid Transmissions on which it is installed and replacing it with software version 5500689, which eliminates the issue.
- Remedies can commence immediately as software version 5500689 is available as of December 11, 2013. Eaton is working cooperatively with vehicle manufacturers to identify the affected units.
- Eaton will provide the software update for the recalled Hybrid Transmissions at no charge. You must supply a detailed breakdown of actual expenses on a per vehicle basis including the number of hours and the actions taken. Eaton will use its Roadranger Call Center for working with customers and the associated reimbursement. The repair requires downloading new software into the transmission, the estimated repair time is one hour.

WHAT YOU SHOULD DO

Please contact your Eaton Representative or the Roadranger Call Center to have your software version updated for the attached VINs. If there are questions about the VIN list, contact the Roadranger Call Center.

Direct any questions that you may have to your Eaton Customer Support Representative or the Roadranger Call Center (follow prompts to Hybrid Electric support):

Attn: Roadranger Call Center
Eaton Corporation
13100 E. Michigan Avenue
Galesburg, MI 49053
Tel: **800-826-4357**
HybridRTW@eaton.com

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your distributor fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington D.C. 20990 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Eaton Corporation

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Tél
503.745.9009 Téléc

**Janvier 2014
Transport Canada 13-448**

RAPPEL IMPORTANT LIÉ À LA SÉCURITÉ

Objet : Logiciel du module de commande de la boîte de vitesses hybride Eaton

Cet avis vous est envoyé conformément à la Loi sur la sécurité automobile du Canada.

Daimler Trucks North America LLC (DTNA) fournit cette Avis de rappel à l'égard de certains véhicules avec des équipements fabriqués par Eaton Corporation plc ("Eaton"). Les véhicules spécifiques concernés sont le Freightliner Business Class M2, Freightliner Custom Chassis MT45 et MT55 de avec châssis de camionnette plain-pied, et les bus Thomas Built Buses Saf-T-Liner C2 fabriqués entre le 30 septembre 2013, à le 10 décembre 2013, ou qui ont reçu certaines mises à jour le logiciel de boîte de vitesses hybride Eaton lors d'une visite de service du 2 février 2013 au 6 décembre 2013.

DTNA et Eaton ont décidé qu'une défectuosité reliée à la sécurité du véhicule moteur existe pour les véhicules mentionnés ci-dessus.

Pendant les rétrogradations où la vitesse actuelle reste engagée ou se réengage en raison d'une panne mécanique ou de système, la logique du logiciel dans le module de commande du système hybride de la boîte de vitesses peut potentiellement entraîner l'accélération involontaire pendant une rétrogradation. Ce défaut peut provoquer un accident sans avertissement préalable.

Eaton remédie ce défaut par la suppression des logiciels de module de contrôle hybride versions 5500682 et 5500683, le remplaçant par le logiciel version 5500689, ce qui élimine le problème.

S'il vous plaît contacter un centre Eaton autorisé pour faire exécuter ce rappel. Voir l'avis de rappel Eaton ci-inclus pour plus de détails.

Pour toute question concernant ce rappel, s'il vous plaît contacter Eaton au 1-800-826-4357.

SERVICE DES CAMPAGNES DE GARANTIE
Pièce jointe



Powering Business Worldwide

BACKED BY
Roadranger
SUPPORT

P.O. Box 4013 | Kalamazoo, Michigan 49003

RAPPEL IMPORTANT LIÉ À LA SÉCURITÉ

janvier 10, 2014

OBJET : Rappel de sécurité pour boîte de vitesses hybride Eaton

Nom du modèle : Boîtes de vitesses hybride Eaton

Ce rappel s'applique seulement aux versions de logiciel de Module de contrôle hybride 5500682 ou 5500683.

Modèles concernés :

EH-6E606B-CD; EH-6E606B-U; EH-6E606B-UP; EH-6E706B-UPG; EH-6E606B-T;
EH-6E606B-CDG; EH-6E606B-P; EH-6E606B-CDR; EH-6E606B-PBD; EH-6E706B-PSB; EH-6E606B-PBD

Cher client :

Cet avis vous est envoyé conformément aux exigences de la National Traffic and Motor Vehicle Safety Act.

Eaton Corporation plc ("Eaton") a décidé que le défaut qui a trait à la sécurité des véhicules à moteur existe dans certains des modèles de boîtes de vitesses hybrides susmentionnés produites à partir de Août 2010 à Décembre 2013, avec les révisions de logiciels mentionnés ci-dessus.

RAISON POUR LE RAPPEL

Ce défaut apparaît dans les boîtes de vitesses référencées ci-dessus contenant les versions de logiciels de module de contrôle hybride 5500682 ou 5500683. La version 5500682 du logiciel a été publiée le 2 Février,

2013 aux organisations de service de terrain de Eaton pour le téléchargement dans les boîtes de vitesses en tant que mise à jour du logiciel sur le terrain. La version 5500683 du logiciel a été publié sur le terrain le 20 juin 2013. L'organisation de service de terrain de Eaton suit électroniquement tous les téléchargements de la version du logiciel par le numéro d'identification du véhicule (NIV). La version du logiciel n'est pas visible de l'extérieur sur la boîte de vitesses. La liste des numéros VIN impactées est attachée.

Les symptômes de véhicules peuvent se produire dans les rétrogradations de la boîte de vitesses hybride Eaton chargée avec les versions 5500682 ou 5500683 des logicielles des modules de contrôle hybride. Pendant les rétrogradations où la vitesse actuelle reste engagée ou se réengage en raison d'une panne mécanique ou de système, la logique du logiciel dans le module de commande du système hybride de la boîte de vitesses peut potentiellement entraîner l'accélération involontaire pendant une rétrogradation.

CE QUE NOUS FERONS

- Eaton va remédier au défaut par la suppression du logiciel de contrôle du module hybride versions 5500682 et 5500683 de toutes les boîtes de vitesses hybrides sur lesquels il est installé et le remplacer par la version 5500689 du logiciel, ce qui élimine le problème.
- L'application de ce remède peut commencer immédiatement car la version 5500689 du logiciel est disponible depuis le 11 décembre 2013. Eaton travaille en collaboration avec les constructeurs automobiles pour identifier les unités touchées.
- Eaton fournira sans frais la mise à jour logicielle pour les boîtes de vitesses hybrides rappelées. Vous devez fournir une ventilation détaillée des dépenses réelles par véhicule, y compris le nombre d'heures et les mesures prises. Eaton utilisera son Call Center Roadranger pour travailler avec les clients et effectuer le remboursement associé. La réparation nécessite le téléchargement de nouveaux logiciels dans la boîte de vitesses; le temps de réparation estimé est d'une heure.

CE QUE VOUS DEVRIEZ FAIRE

S'il vous plaît contacter votre représentant Eaton ou le Centre d'appels Roadranger afin d'obtenir votre version du logiciel mis à jour pour les NIV touchés. Si il y a des questions sur le NIV, contacter le Centre d'appels Roadranger.

Diriger toutes les questions que vous pourriez avoir à votre représentant du service clientèle Eaton ou le Centre d'appel Roadranger (suivez les invites pour atteindre le soutien hybride électrique) :

Attn : Roadranger Call Center
Eaton Corporation
13100 E. Michigan Avenue
Kalamazoo, MI 49053
Tél : **800-826-4357**
Hybrid.RTW@eaton.com

Nous regrettons tout inconvenient que cette action pourrait vous causer. Cependant, nous sommes préoccupés par votre sécurité. Si votre distributeur est incapable ou néglige de corriger la défectuosité gratuitement et dans un délai raisonnable, vous pourriez porter plainte par écrit à l'administrateur de National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590 ou encore appeler la ligne d'assistance Vehicle Safety au 1-888-327-4236 (TTY : 1-800-424-9153); ou à <http://www.safercar.gov>.

Cordialement,

Eaton Corporation

Eaton Hybrid Transmission Control Module Software Recall

Affected VINs

Serial	VIN	Owner	Address	City	State	Zip
AK1809	1FVACXDT19H	FOOD SERVICES OF AMERICA	350 S PACIFIC HWY	WOODBURN	OR	97071
AL3198	4UZACYDT09C	UNITED PARCEL SERVICE	15 OREGON AVE	PHILADELPHIA	PA	19148
AP3584	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3586	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3587	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3588	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3589	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3590	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3591	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3592	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3593	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3594	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3596	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3597	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3598	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3599	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3600	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3601	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3605	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3606	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3607	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3609	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3611	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3612	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3614	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3615	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3616	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3617	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3618	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3619	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328

Serial	VIN	Owner	Address	City	State	Zip
AP3620	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3621	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3622	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3624	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3625	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3626	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3627	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3629	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3631	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3633	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3635	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3639	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3641	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3643	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3644	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3645	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3646	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3647	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3648	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3649	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3650	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3651	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3652	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3653	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3654	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3655	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3656	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3658	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3659	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3660	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3661	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3663	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3664	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328

Serial	VIN	Owner	Address	City	State	Zip
AP3665	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3667	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3668	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3669	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3670	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3671	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3673	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3674	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3675	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3676	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3677	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3679	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3681	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3682	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3683	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3685	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3686	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3687	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3688	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3691	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3693	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3694	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3695	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3696	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3697	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3698	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3699	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3700	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3701	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3703	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3704	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3705	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3706	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328

Serial	VIN	Owner	Address	City	State	Zip
AP3707	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3708	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3711	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3712	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3713	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3715	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3716	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3718	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3720	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3721	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3722	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3728	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3729	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3731	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3734	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3735	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3736	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3738	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3739	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3741	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3742	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3744	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3747	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3748	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3749	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3750	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3754	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3755	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3758	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3759	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3760	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3761	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3763	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328

Serial	VIN	Owner	Address	City	State	Zip
AP3764	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3765	4UZACYDT5AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3766	4UZACYDT7AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3767	4UZACYDT9AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3768	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3769	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3771	4UZACYDT0AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3772	4UZACYDT2AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3773	4UZACYDT4AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3774	4UZACYDT6AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3775	4UZACYDT8AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3776	4UZACYDTXAC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3777	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3778	4UZACYDT3AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AP3780	4UZACYDT1AC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AS3746	4UZADADT7BC	SOUTH CAROLINA DEPT OF ED	1429 SENATE ST	COLUMBIA	SC	29201
AS3886	4UZACYDT9AC	PORTLAND, CITY OF	2835 N KERBY ST	PORTLAND	OR	97227
AS3887	4UZACYDT0AC	PORTLAND, CITY OF	2835 N KERBY ST	PORTLAND	OR	97227
AS3888	4UZACYDT2AC	PORTLAND, CITY OF	2835 N KERBY ST	PORTLAND	OR	97227
AS3889	4UZACYDT4AC	PORTLAND, CITY OF	2835 N KERBY ST	PORTLAND	OR	97227
AT8100	4UZADADT1BC	FORT WORTH ISD	100 N UNIVERSITY DR	FORT WORTH	TX	76107
AT8115	4UZADADT3BC	FORT WORTH ISD	100 N UNIVERSITY DR	FORT WORTH	TX	76107
AW3991	1FVACXDT9BH	KING COUNTY PURCHASING	155 MONROE AVE	RENTON	WA	97015
AW9878	1FUBCYDT2BD	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AX0218	4UZACYDT3BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0225	4UZACYDT0BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0229	4UZACYDT8BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0230	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0241	4UZACYDT9BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0242	4UZACYDT0BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0250	4UZACYDTXBC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0257	4UZACYDT2BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0260	4UZACYDT2BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328

Serial	VIN	Owner	Address	City	State	Zip
AX0262	4UZACYDT6BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0265	4UZACYDT1BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0269	4UZACYDT9BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0282	4UZACYDT1BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0284	4UZACYDT5BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0287	4UZACYDT0BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0288	4UZACYDT2BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0289	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0291	4UZACYDT2BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0292	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0295	4UZACYDTXBC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0296	4UZACYDT1BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0297	4UZACYDT3BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0301	4UZACYDT1BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0304	4UZACYDT7BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0305	4UZACYDT9BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0308	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0309	4UZACYDT6BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0310	4UZACYDT2BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0311	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX0312	4UZACYDT6BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
AX1291	1FUBCYDT2BD	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AX2166	1FVACXDT1BH	SYSCO SAN FRANCISCO	5900 STEWART AVE	FREMONT	CA	94538
AX2168	1FVACXDT5BH	SYSCO SAN FRANCISCO	5900 STEWART AVE	FREMONT	CA	94538
AX2169	1FVACXDT7BH	SYSCO SAN FRANCISCO	5900 STEWART AVE	FREMONT	CA	94538
AX2171	1FUBCXDT5BD	SYSCO VENTURA, INC.	3100 STURGIS RD	OXNARD	CA	93030
AX2176	1FUBCXDT4BD	SYSCO SAN DIEGO, INC	12180 KIRKHAM RD	POWAY	CA	92064
AX2177	1FUBCXDT6BD	SYSCO SAN DIEGO, INC	12180 KIRKHAM RD	POWAY	CA	92064
AX2178	1FUBCXDT8BD	SYSCO SAN DIEGO, INC	12180 KIRKHAM RD	POWAY	CA	92064
AX2372	1FUBCYDT7BD	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AX4085	1FVACXDT0BH	AMERIGAS	460 N GULPH RD	KING OF PRUSSIA	PA	19406
AX4097	1FVACXDT7BH	AMERIGAS	460 N GULPH RD	KING OF PRUSSIA	PA	19406
AX9601	4UZACDDU1BC	UNIVERSITY OF WASHINGTON	4549 25TH AVE NE	SEATTLE	WA	98105

Serial	VIN	Owner	Address	City	State	Zip
AY3342	1FVACWDT3BH	INTERNATIONAL LIMOUSINE SERVIC	2300 T ST NE	WASHINGTON	DC	20002
AY6823	1FUBCXDT3BH	SYSCO BALTIMORE, LLC	8000 DORSEY RUN RD	JESSUP	MD	20794
AY6828	1FUBCXDT2BH	SYSCO VIRGINIA, LLC	5081 S VALLEY PIKE	HARRISONBURG	VA	22801
AY6833	1FUBCXDT6BH	SYSCO CINCINNATI, LLC	10510 EVENDALE DR	CINCINNATI	OH	45241
AY6930	1FUBCXDT4BH	SYSCO ATLANTA, LLC	2225 RIVERDALE RD	COLLEGE PARK	GA	30349
AY6931	1FUBCXDT6BH	SYSCO ATLANTA, LLC	2225 RIVERDALE RD	COLLEGE PARK	GA	30349
AY6932	1FUBCXDT8BH	SYSCO ATLANTA, LLC	2225 RIVERDALE RD	COLLEGE PARK	GA	30349
AY7229	1FUBCYDTXBH	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AY7238	1FUBCYDT0BH	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AY7239	1FUBCYDT2BH	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AY7240	1FUBCYDT9BH	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AY7243	1FUBCYDT4BH	COCA COLA REFRESHMENTS USA,INC	PO BOX 723040	ATLANTA	GA	311139004
AY8601	1FUBCYDT9BH	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AY8602	1FUBCYDT0BH	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AY8603	1FUBCYDT2BH	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AY8604	1FUBCYDT4BH	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AY8605	1FUBCYDT6BH	NEW BERN TRANSPORT CORP	9800 CROSSPOINT BLVD	INDIANAPOLIS	IN	462561549
AY8839	1FVACXDT7BH	SYSCO ATLANTA, LLC	2225 RIVERDALE RD	COLLEGE PARK	GA	30349
BA8116	1FVACXDTXBD	PORTLAND, CITY OF	2835 N KERBY ST	PORTLAND	OR	97227
BA8174	4UZACYDT9BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
BA8180	4UZACYDT4BC	UNITED PARCEL SERVICE OF AMERI	55 GLENLAKE PKY NE	ATLANTA	GA	30328
BB2453	1FVACXDT3BH	OCONOMOWOC UTILITY SALES	412 RANDOLPH DR	APPLETON	WI	54913
BB4507	1FVACXDTXBH	AUSTIN ENERGY	721 BARTON SPRINGS	AUSTIN	TX	78704
BB4508	1FVACXDT1BH	AUSTIN ENERGY	721 BARTON SPRINGS	AUSTIN	TX	78704
BC5533	1FUBCXDT8CH	SYSCO CENTRAL PENNSYLVANIA	3905 COREY RD,UNION SQ. IND. PARK	HARRISBURG	PA	17109
BD0553	1FVACXDT7CH	SYSCO METRO NEW YORK, LLC	20 THEODORE CONRAD DR-LIBERTY IND.PRK	JERSEY CITY	NJ	7305
BE5511	4UZACYDTXBC	ARAMARK UNIFORM SERVICES	115 N 1ST ST	BURBANK	CA	91510
BE5539	4UZACDDU8BC	UTILIMASTER CORP	PO BOX 585	WAKARUSA	IN	46573
BE5541	4UZACDDU6BC	ARAMARK UNIFORM SERVICES	115 N 1ST ST	BURBANK	CA	91510
BE9867	4UZADADT6CC	WARREN COUNTY BOARD OF EDUCATI	PO BOX 51810	BOWLING GREEN	KY	421026810
BE9868	4UZADADT8CC	WARREN COUNTY BOARD OF EDUCATI	PO BOX 51810	BOWLING GREEN	KY	421026810
BE9869	4UZADADTXCC	WARREN COUNTY BOARD OF EDUCATI	PO BOX 51810	BOWLING GREEN	KY	421026810
BF7411	1FUBCXDT0CH	SYSCO WEST COAST FLORIDA,INC	3000 69TH ST E	PALMETTO	FL	34221

Serial	VIN	Owner	Address	City	State	Zip
BH4265	4UZACYDT1BC	TACOMA, CITY OF PUBLIC UTIL	PO BOX 11007	TACOMA	WA	984111007
BH4266	4UZACYDT3BC	TACOMA, CITY OF PUBLIC UTIL	PO BOX 11007	TACOMA	WA	984111007
BH8015	4UZADADT1CC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BH8016	4UZADADT3CC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BJ5934	1FVACXDT4CH	NIAGARA MOHAWK A NATIONAL GRID	175 E OLD COUNTRY RD	HICKSVILLE	NY	11801
BJ8468	1FVACYDT8CH	WICHITA, CITY OF	455 N MAIN ST	WICHITA	KS	67202
BK2838	1FUBCXDT9CH	SYSCO MINNESOTA, INC	2400 COUNTY RD J	ST PAUL	MN	55112
BK2839	1FUBCXDT0CH	SYSCO MINNESOTA, INC	2400 COUNTY RD J	ST PAUL	MN	55112
BL1355	1FVACXDU1CH	URBAN IMPACT RECYCLING LTD	15360 KNOX WAY	RICHMOND	BC	V6V 3A6
BM3312	4UZADADT2CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM3313	4UZADADT4CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM3314	4UZADADT6CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM3315	4UZADADT8CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM3902	4UZADADT1CC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BM3903	4UZADADT3CC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BM4670	4UZADADT0CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM4671	4UZADADT2CC	LAMERS BUS LINES INC	2407 S POINT RD	GREEN BAY	WI	543135498
BM6228	4UZACYDT1CC	RENTON, CITY OF	3555 NE 2ND ST	RENTON	WA	98056
BT1874	4UZADADT4DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1875	4UZADADT6DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1876	4UZADADT8DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1877	4UZADADTXDC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1878	4UZADADT1DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1879	4UZADADT3DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1880	4UZADADTXDC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1881	4UZADADT1DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1883	4UZADADT5DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1884	4UZADADT7DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BT1885	4UZADADT9DC	RITEWAY BUS SERVICE	W201 N13900 FOND DU LAC AVE	RICHFIELD	WI	53076
BU4248	4UZADADT0DC	USD #500- KANSAS CITY	6126 PARALLEL	KANSAS CITY	KS	66101
BW4793	4UZADADT4DC	JEFFERSON COUNTY PUBLIC SCHOOL	PO BOX 35340	LOUISVILLE	KY	40232
BZ6437	1FVHCYDT2DH	S A Q SER DES ACHATS	7500 RUE TELLIER	MONTREAL	QC	H1M3W2
BZ6438	1FVHCYDT4DH	S A Q SER DES ACHATS	7500 RUE TELLIER	MONTREAL	QC	H1M3W2

Serial	VIN	Owner	Address	City	State	Zip
BZ6439	1FVHCYDT6DH	S A Q SER DES ACHATS	7500 RUE TELLIER	MONTREAL	QC	H1M3W2
BZ8486	1FVACXDT9DH	ALAMEDA, COUNTY OF	165 13TH ST	OAKLAND	CA	94612
BZ8608	4UZACYDT5DC	LAKE OSWEGO CITY OF	380 A AVE	LAKE OSWEGO	OR	97034
FB9292	1FVACYDT1DH	ALTEC INDUSTRIES	2106 S RIVERSIDE RD	ST JOSEPH	MO	645079799
FB9339	1FVACYDT1DH	ALTEC INDUSTRIES	2106 S RIVERSIDE RD	ST JOSEPH	MO	645079799
FD7293	1FVACYDT5DH	PENNSYLVANIA, DEPT OF TRANS	17TH AND ARSENAL BLVD	HARRISBURG	PA	17105
FJ0376	1FVACXDT8DH	ENVIRONMENT CANADA	355 RIVER ROAD S	OTTAWA	ON	K1V 1C7
FL1143	1FVACXDT0EH	WICHITA, CITY OF	455 N MAIN ST	WICHITA	KS	67202
FS3234	1FVACWDT4EH	AUBURN UNIVERSITY	1967 WIRE RD	AUBURN	AL	36832
FS3238	1FVACWDT1EH	CHAMPION BUS INC (BB)	331 GRAHAM RD	IMLAY CITY	MI	48444
FS3240	1FVACWDTXEH	AUBURN UNIVERSITY	1967 WIRE RD	AUBURN	AL	36832
FS3242	1FVACWDT3EH	CHAMPION BUS INC (BB)	331 GRAHAM RD	IMLAY CITY	MI	48444
FU4691	1FVACYDT0EH	CHICAGO, CITY OF	1685 N THROOP ST	CHICAGO	IL	60622
FU4692	1FVACYDT2EH	CHICAGO, CITY OF	1685 N THROOP ST	CHICAGO	IL	60622
FU4693	1FVACYDT4EH	CHICAGO, CITY OF	1685 N THROOP ST	CHICAGO	IL	60622
FV6038	1FVACWDT4EH	TEREX UTILITIES SOUTH (BB)	PO BOX 1150	WATERTOWN	SD	57201
FV7678	1FVACYDT7EH	CHICAGO, CITY OF	1685 N THROOP ST	CHICAGO	IL	60622
FV9103	1FVACWDT4EH	INTERIOR REMOVAL SPECIALISTS	9309 RAYO AVE	SOUTH GATE	CA	902803612
FV9104	1FVACWDT6EH	INTERIOR REMOVAL SPECIALISTS	9309 RAYO AVE	SOUTH GATE	CA	902803612
FV9105	1FVACWDT8EH	INTERIOR REMOVAL SPECIALISTS	9309 RAYO AVE	SOUTH GATE	CA	902803612
FV9106	1FVACWDTXEH	INTERIOR REMOVAL SPECIALISTS	9309 RAYO AVE	SOUTH GATE	CA	902803612
FW1548	1FVACWDT8EH	MOTOR TRANSPORT DEPARTMENT	MCAS CHERRY POINT PSC 8006 BLDG 160 CURI	CHERRY POINT	NC	28533
FW2054	1FVFCYDT8EH	SAN FRANCISCO FOOD BANK	900 PENNSYLVANIA AVE	SAN FRANCISCO	CA	941073446
FY2016	1FVACWDT3EH	LOS RIOS COMMUNITY COLLEGE DIS	1919 SPANOS CT	SACRAMENTO	CA	95825
FY2037	1FVACWDT0EH	G S A	11710 STATESVILLE BLVD	CLEVELAND	NC	27013
FY5359	1FVACWDU3EH	G S A	11710 STATESVILLE BLVD	CLEVELAND	NC	27013
FY7790	1FVACXDT5EH	VENTURA COUNTY FLEET SERVICES	11201 RIVER BANK DR # A-1	VENTURA	CA	930043266
FY7791	1FVACXDT7EH	VENTURA COUNTY FLEET SERVICES	11201 RIVER BANK DR # A-1	VENTURA	CA	930043266