



PREVOST

SAFETY RECALL

SR13-72

DATE : DECEMBER 2013	SECTION : 03 - Fuel
SUBJECT: ACCELERATOR PEDAL INSPECTION	

APPLICATION

NOTICE TO SERVICE CENTERS <i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN 
H3-41, H3-45 coaches Model Year: 2009 - 2010	From 2PCH334919C71 1412 up to 2PCH33492AC71 1472 incl.
X3-45 coaches Model Year: 2009	From 2PCG334999C72 9605 up to 2PCG334989C72 9630 incl.
H3-45 VIP motorhomes Model Year: 2008	From 2PCV334938C71 1414 up to 2PCV334938C71 1459 incl.
XLII-45 Entertainer Model Year: 2009	From 2PCW334969C72 9606 up to 2PCW334969C72 9623 incl.
XLII-45 motorhomes Model Year: 2009	From 2PCY334979C72 9607 up to 2PCY334969C72 9632 incl.
This Safety Recall does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this recall will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION

On the vehicles affected by this campaign, it is necessary to check the accelerator pedal serial number as described in Part 1 of the campaign. If the serial number is included in the range of affected accelerator pedal, your accelerator pedal must be replaced as described in Part 2.

DESCRIPTION OF DEFECT: Mechanical springs are used to return the accelerator pedal to idle position when the driver lifts his foot off of the accelerator pedal. On the suspect pedals, the edge of the raw material that was used to make the spring may have a poor edge condition that can result in a local stress riser and a fracture origination point. As a result, a crack may occur that can lead to a broken spring.

FAILURE CONSEQUENCE: If both springs were to fail, it could result in the pedal not returning to idle. If this occurs, this may present a risk of a vehicle crash under certain conditions if the driver does not have time to take action by applying the service brakes, switching the transmission into neutral, applying the park brake, or cutting off the ignition key.


PART 1 – CHECKING ACCELERATOR PEDAL SERIAL NUMBER



DANGER

Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Check the serial number on the accelerator pedal assembly.
2. If the accelerator pedal serial number matches with a serial number found in the following list, a replacement of the accelerator pedal is needed. To do so, perform Part 2 of this campaign.
3. If your accelerator pedal serial number is not within the range of affected accelerator pedal, no replacement is needed. No other verification or repair is necessary.



DEFECTIVE ACCELERATOR PEDAL SERIAL NUMBERS

080218-500174	080218-500182	080218-500190	080218-500198
080218-500175	080218-500183	080218-500191	080218-500199
080218-500176	080218-500184	080218-500192	080218-500200
080218-500177	080218-500185	080218-500193	080218-500201
080218-500178	080218-500186	080218-500194	080218-500202
080218-500179	080218-500187	080218-500195	080218-500203
080218-500180	080218-500188	080218-500196	080218-500204
080218-500181	080218-500189	080218-500197	080218-500205

WARRANTY

PART 1, INSPECTION ONLY: This inspection is covered by Prevost's normal warranty. We will reimburse you 1/4 hour(s) (0.25) of labor upon receipt of a completed A.F.A. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under service \ warranty section). Use Claim Type: "Bulletin/Recall" and select "Safety Recall SR13-72".

Should you only wish to close the safety recall (without reimbursement), fill-in the "Safety Recall Certification Sheet" provided with this bulletin and return it to our warranty department by Email at prevost.onlinewarranty@volvo.com or by fax at 418-831-9301.

PART 2 –ACCELERATOR PEDAL REPLACEMENT

MATERIAL


Order the following parts:

Part No.	Description	Qty
531483	ACCELERATOR PEDAL	1


NOTE

Material can be obtained through regular channels.

1. Remove accelerator pedal mounting bolts (3x).



2. Unscrew the electrical harness P-clamps (2x).
3. Unplug the connector from the acceleration pedal. Unless it is in bad condition, reuse the existing harness and connect it to new accelerator pedal.
4. Plug connector to new acceleration pedal. Secure P-clamps onto the new acceleration pedal.
5. Bolt the new accelerator pedal to the floor using the existing hardware.
6. Start the engine. With the parking brake applied and transmission in neutral position (N), test the accelerator pedal for proper functioning.



PARTS DISPOSITION

All replaced parts must be returned to Prevost according to the Return Shipping Instructions available on www.prevostcar.com (under service / warranty section) for full reimbursement. A copy of the warranty claim form must be enclosed with the shipment.

WARRANTY

Part 1 & Part 2, INSPECTION AND REPLACEMENT: This repair is covered by Prevost's normal warranty. We will reimburse you the parts and 3/4 hour(s) (0.75) of labor upon receipt of the replaced part and a completed A.F.A. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under service \ warranty section). Use Claim Type: "Bulletin/Recall" and select "Safety Recall SR13-72".


OTHER

VBC Bulletin	n/a
Fail Code	03.08
Defect Code	09
Syst.Cond.	R
Causal Part	531483

Access all our Service Bulletins on
<http://prevostparts.volvo.com/technicalpublications/en/pub.asp>
or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type
"ADD" in the subject to receive our warranty bulletins by e-mail.



**PREVOST**

Safety Recall Certification Sheet (Ref: SR13-72)

VEHICLE SERIAL NUMBER:

2	P	C															
---	---	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PERFORMED BY		OWNER/OPERATOR	
We hereby certify that Safety Recall Instructions with regard to Safety Recall SR13-72 have been performed.			
Name: _____		Name: _____	
Addr: _____		Addr: _____	
Phone: _____		Phone: _____	
Fax: _____		Fax: _____	
Signature : _____	_____	Signature : _____	_____
Date: _____	_____	Date: _____	_____

If the information mentioned above is incorrect or you are not the owner of this vehicle anymore, please fill this section and return to sender.

NEW OWNER:

BUSINESS:

ADDRESS (including County):

TELEPHONE:

FAX:

Please return this completed document with your A.F.A. form