



**AUTOMOBILE DIVISION**  
American Honda Motor Co., Inc.  
1919 Torrance Blvd., - P.O. Box 2215  
Torrance, CA 90509-9870

October 2014

RE: 2007-08 Fit  
NHTSA Recall 13V-260

**IMPORTANT**

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear Honda Fit Owner:

**What is the reason for this notice?**

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. The power window master switch repair conducted in 2010, pursuant to NHTSA recall 10V-033, was not sufficient in preventing water intrusion into the switch. Under severe conditions, water may still enter the driver's window and reach the power window master switch, resulting in impaired function of the switch. If the switch is damaged as a result of the water intrusion, it may result in failure of the switch and overheating. An overheating switch can cause smoke, melting, or fire.

**What should you do?**

Please contact any authorized Honda dealer to schedule a service appointment. The dealer will replace the vehicle's power window master switch. This work will be done *free of charge*.

**If you have questions**

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 888-234-2138 and select option 2. You may also find this information at [www.Hondacars.com](http://www.Hondacars.com).

We apologize for any inconvenience this safety recall may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Honda vehicle.

Sincerely,

**American Honda Motor Co., Inc.  
Honda Automobile Division**

**NOTICE: If this is a leased vehicle, please forward this notice to the lessee.**

Octubre del 2014

RE: Fit 2007–2008  
Campaña de seguridad NHTSA 13V-260

**IMPORTANTE**

- **Su vehículo está incluido en una campaña de seguridad y debe completar el servicio de la campaña lo más pronto posible.**
- **Cualquier concesionario autorizado Honda podrá realizar el servicio de la campaña de seguridad, sin costo alguno.**

Estimado propietario de un vehículo Honda Fit:

**¿Cuál es el motivo de esta notificación?**

Nuestros registros indican que no se ha completado una CAMPAÑA DE SEGURIDAD en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. La reparación del interruptor maestro de las ventanas eléctricas realizada conforme a la Campaña de seguridad NHTSA 10V-033 del 2010 no fue suficiente para prevenir la entrada del agua al interruptor. Bajo condiciones severas, todavía puede ingresar agua en la ventana del conductor y llegar hasta el interruptor maestro de las ventanas eléctricas resultando en un funcionamiento deficiente del interruptor. Si el interruptor se daña como resultado del ingreso de agua, esto puede causar falla del interruptor y recalentamiento. Un interruptor recalentado puede causar humo, que se derrita o fuego.

**¿Qué debe hacer?**

Por favor comuníquese con cualquier concesionario autorizado Honda para programar una cita de servicio. El concesionario reemplazará el interruptor maestro de las ventanas eléctricas de su vehículo. Este trabajo se realizará *sin costo alguno*.

**Si tiene preguntas**

Si tiene preguntas acerca de esta notificación o necesita asistencia para ubicar un concesionario, comuníquese con Atención al Cliente de Automóviles Honda al 888-234-2138 y seleccione la opción 2. Usted también puede encontrar esta información en [www.Hondacars.com](http://www.Hondacars.com).

Le pedimos disculpas por cualquier inconveniente que esta campaña de seguridad pudiera causarle. Nosotros estamos tomando esta acción en el interés de su seguridad y satisfacción continua con su vehículo Honda.

Atentamente,

**American Honda Motor Co., Inc.**  
**División Automotriz de Honda**

**AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.**

---

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #13-090  
JA7



**AUTOMOBILE DIVISION**  
 American Honda Motor Co., Inc.  
 1919 Torrance Blvd., - P.O. Box 2215  
 Torrance, CA 90509-9870

VEHICLE IDENTIFICATION NUMBER ▶ XXXXXXXXXXXXXXXXXXXX JA7



JA7

\*\*\*\*\*AUTO\*\*3-DIGIT 907



▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

**INFORMATION CHANGE CARD**

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

XXXXXXXXXXXXXXXXXXXX

◀ VEHICLE IDENTIFICATION NUMBER JA7

**PLEASE SIGN AND RETURN THIS CARD ONLY IF YOU HAVE MADE CHANGES**

I no longer own the vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other: \_\_\_\_\_

**Nota:**

Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente al 800-999-1009 y seleccione la opción 4.

Signature: **X**

Date: \_\_\_\_\_

**SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED**



