
[View online](#)



Schedule service for your vehicle's Recall today.

Your safety is our priority.

[BUTTON] Schedule appointment.



A Recall has been issued for your vehicle's Rear Crossmember.

This notice applies to your vehicle, VIN ending in: 272785



What is the problem?



During the winter, road salt and water can enter portions of the rear crossmember leading to corrosion. If the connection between the rear crossmember and control arm separates due to corrosion, handling of the vehicle may be adversely affected, **increasing the risk of a crash.**



What will Hyundai do?



Your Hyundai dealer will inspect and treat the rear crossmember with rust-proofing material. If specified levels of corrosion damage have occurred, the rear crossmember will be replaced. This procedure will be performed at **NO CHARGE** to you. **For your safety, schedule an appointment as soon as possible.**

[BUTTON] Schedule appointment.



For more information:

If you would like more information on the details of this important recall including affected vehicles or frequently asked questions, you may view the [official campaign information here](#).



[HYUNDAIUSA.COM](#) [PRIVACY](#)



You are receiving this notice in accordance with the National Traffic and Motor Vehicle Safety Act because our records indicate that you own or lease the vehicle identified by the VIN on this notice.

This is an outbound email only. Please do not reply to this email.
This message was transmitted by Hyundai Motor America,
10550 Talbert Ave., Fountain Valley, CA 92708.

Hyundai is a registered trademark of Hyundai Motor Company. Hyundai model names are registered trademarks of Hyundai Motor America. All rights reserved.

©2017 Hyundai Motor America.