



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 22, 2014

Mr. Kenneth Bush
Department Manager, Government Relations
Suzuki Motor of America, Inc.
3251 East Imperial Highway
P.O. Box 1100
Brea, CA 92622-1100

NVS-215SM
14V-262

Subject: Headlamp Switch or DRL Module Overheating

Dear Mr. Bush:

This letter serves to acknowledge Suzuki Motor of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SUZUKI/FORENZA/2004-2008
SUZUKI/RENO/2005-2008

Mfr's Report Date: May 16, 2014

NHTSA Campaign Number: 14V-262

Components:

EXTERIOR LIGHTING:HEADLIGHTS

Potential Number of Units Affected: 184,244

Problem Description:

Suzuki Motor of America, Inc. (Suzuki) is recalling certain model year 2004-2008 Forenza vehicles, and 2005-2008 Reno vehicles manufactured from September 1, 2003, through July 30, 2008. In the affected vehicles, heat may be generated in the headlamp switch or daytime running light (DRL) module which could melt the headlamp switch or the DRL module.

Consequence:

If the heat generated within the headlamp switch and DRL module located on the left side of the steering column melts the headlamp switch, there is an increased risk of a fire.

Remedy:

Suzuki will notify owners but the manufacturer has not yet provided a notification schedule. The remedy for this recall campaign is still under development. Owners may contact Suzuki at 1-800-934-0934. Suzuki's number for this recall is XA.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please provide a remedy plan as soon as it has been determined.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is required that owners be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement