



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

July 22, 2014

**1200 New Jersey Avenue SE
Washington, DC 20590**

Mr. Brian Latouf
Director, Field Product Investigations and Evaluations
General Motors LLC
30001 Van Dyke - Mail Code 480-210-2V
Warren, MI 48090-9055

NVS-215KS
14V-341

Subject: Unintended Roof Rail Air Bag Deployment

Dear Mr. Latouf:

This letter serves to acknowledge General Motors LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CADILLAC/CTS/2011

Mfr's Report Date: June 18, 2014

NHTSA Campaign Number: 14V-341

Components:

AIR BAGS
POWER TRAIN:DRIVELINE:DRIVESHAFT

Potential Number of Units Affected: 16,932

Problem Description:

General Motors LLC (GM) is recalling certain model year 2011 Cadillac CTS vehicles manufactured October 18, 2010, to June 2, 2011. In the affected vehicles, vibrations from the drive shaft may cause the vehicle's roll over sensor to command the roof rail air bags to deploy.

Consequence:

If the roof rail air bags deploy unexpectedly, there is an increased risk of crash and injury to the occupants.

Remedy:

GM will notify owners, and dealers will replace the rear drive shaft assembly, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is 14233.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is required that owners be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement