



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 28, 2014

Mr. Brian Latouf
Director, Field Product Investigations and Evaluations
General Motors LLC
30001 Van Dyke - Mail Code 480-210-2V
Warren, MI 48090-9055

NVS-215KS
14V-447

Subject: Seat Height Adjuster Bolt may Fall out

Dear Mr. Latouf:

This letter serves to acknowledge General Motors LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BUICK/LACROSSE/2011-2012
BUICK/REGAL/2011-2012
CADILLAC/SRX/2010-2012
CHEVROLET/CAMARO/2011-2012
CHEVROLET/EQUINOX/2010-2012
GMC/TERRAIN/2010-2012

Mfr's Report Date: July 22, 2014

NHTSA Campaign Number: 14V-447

Components:

SEATS:FRONT ASSEMBLY:POWER ADJUST

Potential Number of Units Affected: 414,333

Problem Description:

General Motors LLC (GM) is recalling certain model year 2011-2012 Buick LaCrosse, Regal and Chevrolet Camaro, as well as certain 2010-2012 Cadillac SRX, Chevrolet Equinox and GMC Terrain vehicles, equipped with power height adjustable driver and passenger seats. In the affected vehicles, the bolt that secures the driver's and passenger's power front seat height adjuster may fall out causing the seat to drop suddenly to the lowest vertical position.

Consequence:

If the driver's seat unexpectedly drops, the distraction and altered seat position may affect the drivers' control of the vehicle, increasing the risk of a crash.

Remedy:

GM will notify owners, and dealers will replace the height adjuster shoulder bolts, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact GM customer service at 1-800-521-7300 (Buick), 1-800-458-8006 (Cadillac), 1-800-222-1020 (Chevrolet), or 1-800-462-8782 (GMC). GM's number for this recall is 14271.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is required that owners be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement