




- Service Program – Dealers will update the vehicles with the latest software to ensure compliance. There will be no charge to owners for this repair.

Attached is the detailed information required by the applicable portions of 49 CFR Part 573 - Defect and Non-Compliance Information Report.

14E-009  
5 PAGES

Please contact me for further information.

Sincerely,

A handwritten signature in black ink that reads "John M. Kobylarz". The signature is written in a cursive style with a large initial "J" and "K".

John Kobylarz  
Safety Compliance Manager  
Jaguar Land Rover North America, LLC

Attachment

49 CFR Part 573 - DEFECT INFORMATION REPORT  
RECALL P042 – Certain 2014 Model Year Land Rover Range Rover Vehicles.

14E-009  
5 PAGES

573.6 (c) (1) - Manufacturer Identification

Manufacturer Corporate Name

Jaguar Land Rover Limited  
Abbey Road  
Whitley  
Coventry  
England  
CV3 4LF

Affiliated U.S. Importing Company

Jaguar Land Rover North America, LLC  
555 MacArthur Boulevard  
Mahwah  
New Jersey 07430

573.6 (c) (2) - Potentially Affected Vehicles

Jaguar Land Rover is conducting a voluntary non-compliance recall involving certain 2014 Model Year Land Rover Range Rover vehicles for front directional indicator lamp software concern built at the Solihull (UK) Assembly Plant from May 7, 2013, to October 10, 2013.

573.6(c) (2) (iv) – Part Numbers, Components affected and Components Final Country of Manufacture

Not applicable as this is a vehicle software related concern.

Plant Manager: Alan Volkaerts  
Telephone number: +44-1217004815

Quality Manager: Chris Scott

Production Facility: Jaguar Land Rover  
Solihull (UK) Assembly Plant  
Solihull  
United Kingdom

UK is the final country of manufacture.



573.6 (c) (10) - Notices, Bulletins, and Other Communications Related to the Defect

Jaguar Land Rover does not plan to make a public statement concerning the subject matter of this action. A copy of the notification letters to dealers and owners from Jaguar Land Rover will be forwarded when available.

14E-009  
5 PAGES

573.6 (c) (11) - Recall Number

Jaguar Land Rover has assigned recall number P042 to this recall action.