

RECEIVED

By Recall Mangement Division at 2:04 pm, Jun 10, 2014

Toyota Motor Engineering &
Manufacturing North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

June 6, 2014

Ms. Nancy Lummen Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Ave, SE
Washington, D.C. 20590

Re: Recall # 14V-168
Certain Toyota and Pontiac Vehicle Spiral Cable Assembly
Part 573, Defect Information Report

Dear Ms. Lewis:

In connection with the above referenced matter, this supplements Toyota's letter of April 9, 2014.
The affected vehicle VIN range and corresponding number of affected vehicles is revised below:

Identification of Affected Vehicles:

| Make/ Car Line | Model Year | Manufac- turer | VIN | | Production Period |
|-------------------|---------------|-------------------|-------|---|--|
| | | | VDS | VIS | |
| Toyota/ RAV4 | 2006- 2008 | TMC | **3*V | 65000001 – 85215928 66000002 – 86089729 | July 28, 2005 through August 5, 2008 |
| Toyota/ Tacoma | 2009- 2010 | TMMBC | ****N | 9M009609 – AM109517 | September 1, 2008 through July 7, 2010 |
| | | TMMCA | | 9Z624003 – AZ749126 | |
| Toyota/ Yaris | 2006- 2010 | TMC | *T**3 | 65007616 – A5312959 71000104 – A1388199 74000003 – A4074494 | July 12, 2005 through March 31, 2010 |

| Make/ Car Line | Model Year | Manufac- turer | VIN | | Production Period |
|------------------------------|---------------|-------------------|----------------|--|--|
| | | | VDS | VIS | |
| Toyota/ Corolla | 2009- 2010 | TMC | B*4*E | 99013744 – A9106869 9J000111 – AJ061151 | July 31, 2007 through July 7, 2010 |
| | | NUMMI | BU4*E | 9Z001002 – AZ386542 | |
| | | TMMC | BU4*E | 9C001054 – AC442191 | |
| Toyota/ Corolla Matrix | 2009- 2010 | TMMC | KE4*E | 9C001041 – AC441446 | January 2, 2008 through June 30, 2010 |
| Toyota/ Highlander | 2008- 2010 | TMC | **41A **3EH | 82000106 – 92151438 A2008099 – A2161035 | March 6, 2007 through July 7, 2010 |
| | | TMMI | **3EH | AS001019 – AS032879 | |
| Pontiac/ Vibe | 2009- 2010 | NUMMI | S*6** | 9Z400002 – AZ420785 | January 22, 2008 through August 18, 2009 |

Note: Although the involved vehicles are within the above VIN ranges, not all vehicles within these ranges were sold in the U.S.

Only Toyota vehicles equipped with spiral cable assemblies that use seven-channel circuits are involved. Other Toyota or Lexus models with similar spiral cable assemblies are not affected, because those spiral cable assemblies contain a Flexible Flat Cable (FFC) with a different number of the channels, or were produced by a different supplier with a different design.

In addition, certain 2005-2009MY Tacoma vehicles involved in recall campaign 12V-092 are not affected because the spiral cables in those vehicles were replaced with the same ones being used in the remedy for this recall.

Total Number of Vehicles Involved:

| | |
|----------------------------|---------|
| Toyota RAV4: | 306,836 |
| Toyota Tacoma: | 41,585 |
| Toyota Yaris, Yaris Sedan: | 402,475 |
| Toyota Corolla: | 524,727 |
| Toyota Matrix: | 62,962 |
| Toyota Highlander: | 97,196 |
| Pontiac Vibe: | 50,632 |

| | |
|--------|-----------|
| Total: | 1,486,413 |
|--------|-----------|

Should you have any questions about this report, please contact me at (310) 468-8551.

Sincerely,

A handwritten signature in black ink, appearing to read "A. Saadat". The signature is fluid and cursive, with a large initial "A" and a long, sweeping underline.

Abbas Saadat
Vice President
Toyota Motor Engineering & Manufacturing
North America, Inc.

cc: J. Timian