

**Part 573 Safety Recall Report****14V-549****Manufacturer Name :** Keystone RV Company**Submission Date :** SEP 08,2014**NHTSA Recall No. :** 14V-549**Manufacturer Recall No. :** 14-216**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : 17400 Hackberry Drive  
Goshen IN 46526

Company phone : 219-642-4590

**Population :**

Number of potentially involved : 198

Estimated percentage with defect : 50

**Vehicle Information :**

Vehicle : 2014-2015 Keystone Hideout 308BHDS Fifth Wheel

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2014 - 2015 Hideout Model 308BHDS Fifth Wheels manufactured in Goshen, IN.

Production Dates : OCT 02, 2013 - AUG 08, 2014

**VIN (Vehicle Identification Number) Range**

Begin : 4YDF30822E7203118

End : 4YDF30820E7205630

 Not sequential VINs

Begin : 4YDF30823F7200195

End : 4YDF30824F7203011

 Not sequential VINs**Description of Defect :**

Description of the Defect : It has been decided the 120V receptacle in the exterior kitchen may not be on GFCI protected circuit.

Description of the Safety Risk : If this condition exists it will lead to an increased risk of electrical shock if an electrical fault exists with an appliance plugged into the receptacle.

Description of the Cause : The wiring for the rear bedroom may have been switched with the outside kitchen causing the outside kitchen to not be on a GFCI protected circuit.

Identification of Any Warning that can Occur : None

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

August 21, 2014 – During a routine audit it was discovered two out of four units did not have GFCI protection on the outside kitchen receptacle.

September 4, 2014 - After review of the wiring it was determined that on some units the wiring for the rear bedroom may have been switched with the outside kitchen causing the outside kitchen to not be on a GFCI protected circuit.

**Description of Remedy :**

Description of Remedy Program : The dealer will verify the outside kitchen receptacle is on a GFCI circuit and if not replace the receptacle with a GFCI type. The service and parts required for this corrective action will be provided at no charge to the owner.

How Remedy Component Differs from Recalled Component : The vehicles that do not have the defect can be tested by tripping the GFCI in the front bathroom and verify the power to the 120V receptacle in the outside kitchen is shut off.

Identify How/When Recall Condition was Corrected in Production : August 21, 2014 – During a routine audit it was discovered two out of four units did not have GFCI protection on the outside kitchen receptacle. All vehicles at Keystone were tested and corrected.

**Recall Schedule :**

Description of Recall Schedule : Keystone will notify dealers and the owners of the recreational vehicles by letter beginning in September 2014 pending NHTSA approval.

Planned Dealer Notification Date : SEP 15, 2014 - SEP 15, 2014

Planned Owner Notification Date : SEP 15, 2014 - SEP 15, 2014

\* NR - Not Reported