

**Part 573 Safety Recall Report****14V-585**

**Manufacturer Name :** Jayco, Inc.  
**Submission Date :** SEP 18,2014  
**NHTSA Recall No. :** 14V-585  
**Manufacturer Recall No. :** 9901221

**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.  
 Address : 903 South Main Street  
 PO Box 460 Middlebury IN 46540  
 Company phone : 800-283-8267

**Population :**

Number of potentially involved : 114  
 Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 Jay Flight Travel Trailer 264BHW (7V) and 267BHSW (7W)  
 Vehicle Type : TRAILERS  
 Body Style :  
 Power Train : NR  
 Descriptive Information : Certain Jayco Jay Flight SLX Travel Trailers with Roof AC Option  
 Production Dates : APR 23, 2014 - JUN 04, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Units built with the Roof AC Option do not have the required venting to allow fresh air into the unit when using the gas range. The Range is vented to the inside and the window does not open. When adding the Roof AC - the roof vent no longer exists  
 Description of the Safety Risk : Possible Inadequate venting for gases from the range  
 Description of the Cause : NR  
 Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR  
 Address : NR  
 NR  
 Country : NR

**Chronology :**

Jayco dealer reported that during PDI they found unit did not have the outside vent for the range. Investigation found that a new option was offered for a Roof AC on the 7V and 7W models, which when installed removed the ceiling vent that complied with venting requirements.

**Description of Remedy :**

Description of Remedy Program : the Existing non opening window will be replaced with window that opens - to allow required ventilation in the travel trailer

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Production changed to venting the range hood to the outside of the units on these models that a roof ac is an option.

**Recall Schedule :**

Description of Recall Schedule : We are working on parts availability

Planned Dealer Notification Date : OCT 17, 2014 - OCT 17, 2014

Planned Owner Notification Date : OCT 17, 2014 - OCT 17, 2014

\* NR - Not Reported