

Part 573 Safety Recall Report**14V-630****Manufacturer Name :** Spartan Motors, Inc.**Submission Date :** OCT 06,2014**NHTSA Recall No. :** 14V-630**Manufacturer Recall No. :** 14019**Manufacturer Information :**

Manufacturer Name : Spartan Motors, Inc.

Address : 1541 Reynolds Road

Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 29

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2015 Spartan Motors Chassis, I Gladiator and MetroStar

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles affected by this recall are emergency response chassis cabs.

Production Dates : FEB 18, 2013 - AUG 05, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Based on information received from Seats, Inc., the affected chassis cabs may not be compliant to S4.3.2.2 of FMVSS 208 which indicates the vehicle shall, at each designated seating position, be equipped with either a Type 1 or a Type 2 seat belt assembly that conforms to FMVSS 209 – Seat Belt Assemblies.

Seats, Inc. has indicated to Spartan Chassis, the seat belt assembly which includes a 17" seat belt buckle installed on their 10-way power seat may not adjust to accommodate the 5th percentile adult female.

Description of the Safety Risk : A lack of adjustment may increase the risk of personal injury in the event of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Seats Incorporated

Address : 1515 Industrial Street
Reedsburg WI 53959

Country : US

Chronology :

NR

Description of Remedy :

Description of Remedy Program : A shorter seat belt buckle will be supplied at no charge.

How Remedy Component Differs from Recalled Component : The seat belt buckle to be supplied as the remedy will be 14" in length. The recalled component is 17".

Identify How/When Recall Condition was Corrected in Production : The shorter seat belt buckle was instituted into production near August 5, 2014.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : OCT 10, 2014 - OCT 10, 2014

Planned Owner Notification Date : NOV 05, 2014 - NOV 05, 2014

* NR - Not Reported